

TO :

ESTIMATE REPORT 1ST Quotation

FAX NO:

03/11/2022 16:17

JOB-NO: 50114607

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

ADDRESS: 383 SIN MING DRIVE

64739522

SINGAPORE 575717 0

VEHICLE DETAILS

LICENSE NO: SHC0655A

TRANS: AUTO

CHASSIS: KMHC851CVKU165171

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI

ENGINE: G4LEKU299327

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,400.00	0.00	1,400.00		1000 Y	
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	160.00	0.00	160.00	30	Y	
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	250.00	0.00	250.00		200 Y	
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	220.00	0.00	220.00	30	Y	
5 TO REFIT REAR REVERSE SENSOR	1.00	100.00	0.00	100.00	X	Y	
6 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	60	Y	
7 TO REMOVE AND REFIT REAR UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR	1.00	350.00	0.00	350.00	X	Y	
8 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200	Y	
9 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	X	Y	
10 TO RESPRAY REAR QUARTER PANEL OUTER	1.00	250.00	0.00	250.00	200	Y	
11 TO RESPRAY REAR DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	
12 TO RESPRAY REAR DOOR PANEL OUTER HANDLE AND COVER	1.00	250.00	0.00	250.00	30	Y	
13 TO RESPRAY REAR DOOR OUTER WAIST LINE MOULDING	1.00	250.00	0.00	250.00	X	Y	
14 TO RESPRAY SIDE SKIRT LH (Root pillar LH)	1.00	250.00	0.00	250.00	200	Y	
TOTAL:		4,350.00	0.00	4,350.00		2150	

MATERIALS

1 REAR BUMPER COVER	X NN	1.00	459.40	91.88	367.52	L	Y	
2 REAR LH BUMPER RETAINER	X NN	1.00	33.10	6.62	26.48	L	Y	
3 REAR LH QUARTER PANEL	— NN	1.00	1,768.30	353.66	1,414.64	✓ L	Y	
4 REAR LH WHEEL RIM COVER	— CUT	1.00	346.40	69.28	277.12	✓ L	Y	
5 REAR LH WHEEL RIM	X NN	1.00	1,091.50	218.30	873.20	L	Y	
6 REAR LH KNUCKLE ARM	X NN	1.00	386.90	77.38	309.52	L	Y	
7 REAR LH KNUCKLE HUB+BEARING	X NN	1.00	454.00	90.80	363.20	L	Y	
8 REAR LH LOWER ARM	X NN	1.00	393.10	78.62	314.48	L	Y	
9 REAR LH ASSIST ARM	X NN	1.00	92.80	18.56	74.24	L	Y	
10 REAR LH SUSPENSION SHOCK ABSORBER	X NN	1.00	230.50	46.10	184.40	L	Y	
11 REAR LH STABILIZER LINK	X NN	1.00	92.10	18.42	73.68	L	Y	
12 REAR LH TRAILING ARM	X NN	1.00	121.00	24.20	96.80	L	Y	

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
13 REAR LH UPPER ARM X NN	1.00	112.20	22.44	89.76	L	Y	
14 REAR LH DOOR PANEL	1.00	2,147.90	429.58	1,718.32	L	Y	
15 REAR LH DOOR FRAME FRONT BLACK TAPE	1.00	7.00	1.40	5.60	L	Y	
16 REAR LH DOOR FRAME REAR BLACK TAPE	1.00	7.00	1.40	5.60	L	Y	
17 REAR LH DOOR FRAME UPPER BLACK TAPE	1.00	9.70	1.94	7.76	L	Y	
18 REAR LH DOOR DIVISION CHANNEL BAR X NN	1.00	53.30	10.66	42.64	L	Y	3429.04
19 REAR BUMPER CLIP SET X NN	1.00	55.00	0.00	55.00	S	Y	
20 REAR DOOR "GOOGLE PLAY STORE" STICKER	1.00	100.00	50.00	100.00	S	Y	
21 REAR DOOR "COMFORT DELGRO" STICKER	1.00	100.00	0.00	100.00	S	Y	
22 REAR BUMPER ADVERTISEMENT STICKER	1.00	250.00	0.00	250.00	S	Y	
23 REAR LH QUARTER PANEL ADVERTISEMENT STICKER	1.00	250.00	0.00	250.00	S	Y	
24 REAR RH QUARTER PANEL ADVERTISEMENT STICKER X NN	1.00	250.00	0.00	250.00	S	Y	
25 REAR DOOR ADVERTISEMENT STICKER	1.00	250.00	0.00	250.00	S	Y	
26 SIDE SKIRT ADVERTISEMENT STICKER X NN	1.00	250.00	0.00	250.00	S	Y	
27 SIDE SKIRT CLIP SET X NN	1.00	50.00	0.00	50.00	S	Y	
28 REAR DOOR OUTER WAIST LINE MOULDING CLIP X NN	1.00	50.00	0.00	50.00	S	Y	
29 FUEL FLAP "PETROL ONLY" STICKER	1.00	100.00	0.00	100.00	S	Y	
30 FUEL FLAP ADVERTISEMENT STICKER	1.00	250.00	0.00	250.00	S	Y	
TOTAL:		9,761.20	1,561.24	8,199.96		530	
TOTAL PARTS & LABOUR :		14,111.20	1,561.24	12,549.96			

EXCESS/LOADING:S\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$ _____

DATE OF SURVEY: _____

SURVEYED BY: Steve (LKK) 4/11/12CONTACT NO: L/S, M. Al-Fay, 6 dgs

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR
STA AUTOCENTRE
TEL: _____

FAX: _____

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

6109.04

L/S - 4887.23
= 4900