

Vehicle Damage Assessment Report for [SHC655A]

Estimate Created: 16/11/2022 22:38 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 16/11/2022 22:59 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	Ergo Insurance	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Ioniq
Engine Type			
License Plate Number	SHC655A	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$4850.00 with 6 days for repair

Insurlogic 1 (16/11/2022 22:58)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR QTR PANEL LH		1	1768.30	-20.00 %	1,414.64
REAR WHEEL RIM COVER		1	346.40	-20.00 %	277.12
REAR DOOR PANEL LH		1	2147.90	-20.00 %	1,718.32
REAR DOOR FRAME FRONT BLACK TAPE LH		1	7.00	-20.00 %	5.60
REAR DOOR FRAME BLACK TAPE LH		1	7.00	-20.00 %	5.60
REAR DOOR FRAME UPPER BLACK TAPE		1	9.70	-20.00 %	7.76

Parts Subtotal 3,429.04

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
GOOGLE PLAY STORE STICKER		1.0	50.00	0.00 %	50.00
ZIG STICKER		1.0	50.00	0.00 %	50.00
REAR BUMPER ADV STICKER		1.0	120.00	0.00 %	120.00
REAR QTR PANEL ADV STICKER		1.0	120.00	0.00 %	120.00
REAR DOOR ADV STICKER		1.0	120.00	0.00 %	120.00
FUEL FLAP STICKER (PETROL)		1.0	30.00	0.00 %	30.00
FUEL FLAP ADV STICKER		1.0	40.00	0.00 %	40.00

Materials Subtotal 530.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
RNR INTERIOR UPHOLSTRY AND REAR WINDSCREEN	RnR	200.00	0.00 %	200.00
CHECK WIRING	RnR	30.00	0.00 %	30.00
WHEEL ALIGNMENT	RnR	60.00	0.00 %	60.00
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	1000.00	0.00 %	1,000.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
ANTI RUST	Full spray	30.00	0.00 %	30.00
REAR BUMPER	Full spray	200.00	0.00 %	200.00
REAR QTR PANEL	Full spray	200.00	0.00 %	200.00
REAR DOOR	Full spray	200.00	0.00 %	200.00
ROOF PILLAR RH	Full spray	200.00	0.00 %	200.00
General Labor Subtotal				1,290.00
Paint Labor Subtotal				830.00
Labor Subtotal				2,120.00

Summary

Repair Cost	6,079.04
Discount(20 %)	(1,229.04)
	4,850.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	4,850.00