

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Nov 2022

Preliminary Advice

Insured	: GBB96P		
Vehicle No			
TP Vehicle		Accident Date	: 03/11/2022
No	: SHC655A		
Make	: HYUNDAI AE IONIQ HEV	Assignment Date	: 04/11/2022
Date of	: 04/11/2022	Est. Duration of	: 6
Inspection		Repair	
Inspection At	: DING AUTOMOTIVE PTE LTD (HQ)		
	31 CORPORATION ROAD		
	SINGAPORE 649825		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,549.96
Revised Amount	:S\$	6,109.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,109.04

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair

:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.