

ASS. REC. BY:

REF:

SMO/ 022 011 049 Kw

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1. B. 1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 5204K Yr Regn: 02, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Priv c.c. 1798Colour M.P. White / Red A/C: Insured / Std / Nil / NASp. Reading 154209 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JTDKB 3FU 003 0938 09Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: Finzer 195/65R15R: Navigator

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 4 mmL/Bal. 5 mmL/Bal. 6 mmD.O.A. 3/11/22D.O.I. 4/11/2022

Survey held at _____

Des. of Damages: FR / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ GIA not ready

10/5 @ 2760.48 Concl 22/5/23 @ 02 days (Red \$9,784.32 / 78%)

Date/Time, File Pass to?

☐

: Prell. Report

1) Typist☒

: Final Report

Date/Time, File Return to?

Days Of Repair: 02 days

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TPLump Sum / I.B.I: (\$ P/P \$2,760.48)

Not Notarized
 Recovery B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5204K

AAD2211-

\$ 2760.48

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

04 NOV 2022

SHC5204K

JTDKB3FU003093809

200303878K

TOYOTA

PRIUS **GEN 4**

03/11/2022

FBT1855P/SOMPO

25/02/2021

PART

- 1 COVER, FRONT BUMPER
- 1 MOULDING, FRONT BUMPER SIDE, RH
- 1 MOULDING, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 COVER, ENGINE UNDER, NO.1
- 1 COVER SUB-ASSY, ENGINE UNDER, NO.2
- 1 EXTENSION, FRONT BUMPER, LH
- 1 EXTENSION, FRONT BUMPER, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 EMBLEM ASSY, MOULDING
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE

LIST		
Bumper	\$	521.00 ✓
R	\$	95.60 X
L	\$	95.60 X
R	\$	110.50 X
R	\$	716.60 ✓
R	\$	246.10 X
L	\$	132.70 X
CM	\$	80.20 ✓
L	\$	82.30 X
L	\$	80.10 X
ERA	\$	472.40 ✓
L	\$	241.90 X
L	\$	120.10 X
L	\$	120.10 X
L	\$	47.50 X
L	\$	47.50 X
R	\$	59.30 X
R	\$	59.30 X
HR	\$	30.20 ✓
CM	\$	422.50 ✓
L R	\$	160.50 X
CM	\$	178.60 ✓
R	\$	105.80 ✓

TOTAL	\$	4,226.40
25%	\$	1,056.60
	\$	3,169.80

Trans-cab Auto Services Pte Ltd

AAD2211-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5204K**Special Nett**

- 1 FRT NUMBER PLATE WITH HOLDER
- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 1 HOOD INSULATOR CLIP
- 1 Engine Under Cover Clip

\$	By 140.00	45sn
\$	nn 95.00	60sn
\$	nn 85.00	X
\$	nn 55.00	X
\$	nn 60.00	X
TOTAL \$	435.00	

TOTAL PARTS \$ 3,604.80**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 4,000.00 3001

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ nn 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ 480.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ nn 250.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 4401

To Check Electrical Lighting Concerned.

\$ 170.00 201

Trans-cab Auto Services Pte Ltd

AAD2211-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5204K

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

	\$	<i>nn</i> 380.00 X
TOTAL	\$	8,940.00

Over All Total	\$	12,544.80
-----------------------	----	------------------

(PART-BY-PART) Repair Days DAYS*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5204K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Nov 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2J02640
Chassis No.:	JTDKB3FU0003093809
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,879.00
Original Registration Date:	25 Feb 2021
First Registration Date:	25 Feb 2021
Transfer Count:	0
Actual ARF Paid:	\$7,131.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2029
PARF Rebate Amount:	\$5,348.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$31,876.00
COE Rebate Amount:	\$25,152.00
Total Rebate Amount:	\$30,500.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Nov 2022

OK