

ASS. REC. BY:

REF: SMO1Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02 days

Res.: Yes or No

Lum Sum: _____

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

S - RS. SI

: Parking

: Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No: SHC 5204KYr Regn: 02, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ToyPrus

c.c

1798Colour M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading 154209

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB 3F4 003 0938 09Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD / Rlm or

Tyre Size: F: Finanz 195/65R15R: Lanvigator

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm

Rear

R/Bal. 4 mmL/Bal. 5 mmL/Bal. 6 mmD.O.A. 3/11/22D.O.I. 4/11/2022

Survey held at _____

Des. of Damages: PR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Not Notarized
Recovery B4 painting

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5204K

AAD2211-

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

04 NOV 2022

SHC5204K

JTDKB3FU003093809

200303878K

TOYOTA

PRIUS **GEN 4**

03/11/2022

FBT1855P/SOMPO

25/02/2021

PART	LIST	
	Qty/Unit	Price
1 COVER, FRONT BUMPER	\$	521.00 ✓
1 MOULDING, FRONT BUMPER SIDE, RH	\$	95.60 X
1 MOULDING, FRONT BUMPER SIDE, LH	\$	95.60 X
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	110.50 ✓
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	716.60 7
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$	246.10 7
1 ABSORBER, FRONT BUMPER, LOWER	\$	132.70 7
1 ABSORBER, FRONT BUMPER ENERGY	\$	80.20 7
1 SUPPORT, FRONT BUMPER SIDE, LH	\$	82.30 X
1 SUPPORT, FRONT BUMPER SIDE, RH	\$	80.10 X
1 COVER, ENGINE UNDER, NO.1	\$	472.40 X
1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	241.90 X
1 EXTENSION, FRONT BUMPER, LH	\$	120.10 X
1 EXTENSION, FRONT BUMPER, RH	\$	120.10 X
1 STAY SUB-ASSY, FRONT BUMPER, RH	\$	47.50 X
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$	47.50 X
1 BRACKET, FRONT BUMPER SIDE, LH	\$	59.30 X
1 BRACKET, FRONT BUMPER SIDE, RH	\$	59.30 X
1 COVER, FRONT BUMPER HOLE, RH	\$	30.20 ✓
1 GRILLE SUB-ASSY, RADIATOR	\$	422.50 ✓
1 EMBLEM ASSY, MOULDING	\$	160.50 X
1 GRILLE, RADIATOR, LOWER NO.1	\$	178.60 ✓
1 EMBLEM ASSY, RADIATOR GRILLE	\$	105.80 ✓
TOTAL	\$	4,226.40
25%	\$	1,056.60
	\$	3,169.80

Trans-cab Auto Services Pte Ltd**AAD2211-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5204K**Special Nett**

1 FRT NUMBER PLATE WITH HOLDER	\$	By 140.00	45m
1SET BUMPER CLIP FRT	\$	nn 95.00	60m
1SET FRNT BUMPER RETAINER CLIP	\$	nn 85.00	X
1 HOOD INSULATOR CLIP	\$	nn 55.00	X
1 Engine Under Cover Clip	\$	nn 60.00	X
TOTAL	\$	435.00	

TOTAL PARTS \$ 3,604.80**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,000.00	300
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	4 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	440
To Check Electrical Lighting Concerned.	\$	170.00	20

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5204K

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

	\$	~ 380.00 X
TOTAL	\$	8,940.00

Over All Total	\$	12,544.80
-----------------------	----	------------------

(PART-BY-PART) Repair Days **_ DAYS**

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 878K

Vehicle Details

Vehicle No.: SHC5204K

Vehicle to be Exported: Yes

Intended Deregistration Date: 03 Nov 2022

Vehicle Make: TOYOTA

Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)

Primary Colour: Red

Manufacturing Year: 2020

Engine No.: 2ZR2J02640

Chassis No.: JTDKB3FU003093809

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,879.00

Original Registration Date: 25 Feb 2021

First Registration Date: 25 Feb 2021

Transfer Count: 0

Actual ARF Paid: \$7,131.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Feb 2029

PARF Rebate Amount: \$5,348.00

Intended COE Rebate Details

COE Expiry Date: 24 Feb 2029

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$31,876.00

COE Rebate Amount: \$25,152.00

Total Rebate Amount: \$30,500.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Nov 2022

OK