-Rasul

Our Ref: SLJ8850R Your Ref: SJJ3754S

s/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP	
		PARTS REPLACEMENT - LIST ITEMS			
1	1	REAR FENDER RH 54		\$ 1,280.00	
2	1	REAR FENDER INNER SHIELD RH	11453	5 267 352.00	
3	1	REAR FENDER LOWER GARNISH RH	41)	\$ 295.00	
4	1	REAR BUMPER de	20%	\$ 1,827.00	
5	1	REAR BUMPER SIDE BRACKET RH	/	\$ 143.00	
6	1	REAR WHEEL RIM RH SCE	3262.80	\$ 5/4-350 890.00	
7	1	REAR ABSORBER RH		\$ 1,042.00	
. 8	1	REAR UPPER ARM RH X AA		\$ 598.00	
9	1	REAR UPPER ARM LINK RH X		\$ 316.00	
10	1	REAR TRAILING ARM RHX		\$ 1,363.00	
11	1	REAR WHEEL HUB RH		\$ 455.00	
12	1	REAR WHEEL HUB BEARING RH	žκ	\$ 396.00	
13	1	REAR LOWER ARM RH X	·	\$ 771.00	
			SUB TOTAL	\$ 9,728.00	
			LESS 20%	\$ 1,945.60	
			TOTAL AMOUNT	\$ ,7,782.40	

Our Ref: SLJ8850R Your Ref: SJJ3754S

s/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. B	Y WORKSHOP
1	1	REAR FENDER INNER SHIELD CLIPS RHALL		\$	30.00
2	1	REAR BUMPER CLIPS No.		\$	60.00
3	1.	REAR WHEEL TYRE RH > A1		\$	280.00
			SUB TOTAL	\$	370.00
			TOTAL PARTS COST	\$	8,152.40

Our Ref: SLJ8850R Your Ref: SJJ3754S

s/NO	DESCRIPTION		EST	. BY WORKSHOP
	LABOUR & PAINTWOR	<u>K</u>		
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO	COMMENCE REPAIRS; PANEL		. /
1	BEAT & RESHAPE THE AFFECTED AREAS AND REPL AND COMPONENTS	ACED THE DAMAGED PARTS	\$	500 1,000.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDED FUNCTIONS	NT AND CHECK FOR PROPER	\$	120.00
3	TO CONDUCT DIGNOSIS FAULT CO	DDE & RESET	\$	80 150.00
4	TO REMOVE & REFIT REAR FENDER QUARTER	glass & mechanism rh	\$	80. 150.00
5	TO REMOVE & REFIT REAR BUMPER R	EVERSE SENSORS	\$	40 100.00
6	TO CONDUCT WHEEL ALIGNMENT	& BALANCING	\$	60 120.00
7	TO REMOVE & REFIT REAR WHEEL I	RIM & TYRE RH	\$	40 60.00
8	TO REMOVE & REFIT REAR SUSP	PENSION RH	\$	250.00
9	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED		\$	600.00
10	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS		\$	30 50.00
11	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)		\$	20 50.00
12	TO VACUUM, WAXING & CLEAN		\$	MAX . 50.00
13	TO PERFORM WATER SEEPAGE TEST ON	REPAIRED PORTIONS	\$	30 58.00
		TOTAL BEFORE GST	\$	10,902.40
		GST 7%	\$	763.17
		TOTAL (PARTS & LABOUR):	\$	11.665.57

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 9,300.00 for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng Claims Director

> LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Paris prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- « Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledges by Repairer

Signature:

Date:

3562.40 350.00

20% 4425.92 \$4,400/6days