



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22011056/Kqy3m4 Date: 13/12/2022 Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	FBQ 3686M	Veh. Inspected	PH 5115M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2203994/THE	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	04/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	FTBCI (M)	c.c	4461	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	LA9L1DAB6GFFBC026	Colour	MULTI COLOUR	
Odometer	508196 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	9 R22.5	PIRELLI	8 mm	
L/H Front Tyre	9 R22.5	PIRELLI	8 mm	
R/H Rear Tyre	9 R22.5 (D)	PIRELLI	8/8 mm	
L/H Rear Tyre	9 R22.5 (D)	PIRELLI	8/8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/11/2022	Inspection Date	08/11/2022	
Survey held at	6 SUNGEI KADUT WAY S' 728768			
Repairer	A T AUTO CONSULTANT			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	