

SERVICE ESTIMATE

34181 - C00001 SL: SERVICE SALES - PC

Mr Yang Shon Yu
15 Park Villas Green

Singapore 545437

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Yang Shon Yu

GST Reg.No:M28920628X

Inv.No. . . : B&P 0 Page 1
Inv.date. . : 31/10/2022
WIP No. . . : 47857
Veh.In/Out:
*Tel.No. . . : Mobile: 96933918
Reg.No. . . : SMQ3818U
Reg.date . . : 24/10/2019
Mileage .. : 0
Chassis No: LVYPS10ADLP078996

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLCE REAR BUMPER,REAR LOWER SPOILER,ETC	0	350.00	0		350.00	S
800	TO PUTTY SPRAY PAINT ON REAR BUMPER,ETC	0	750.00	0		750.00	S
280	RENTAL CAR FOR 3 DAYS	0	600.00	0		600.00	S
	NOTES This Estimate Is Not Meant For Any Insurance Claim Purposes. This Repair Will Take 3 Working Days.	0	0.00	0			S
	NOTES Last 3 parts will be confirmed required replacement after we start work on the car.	0	0.00	0			S
	BUMPER COVER REAR S9	1.0 EA	2753.90			2,753.90	S
	PROTECTING PLATE REA	1.0 EA	439.80			439.80	S
	BLIND RIVET 4.0*21 P	10.0 EA	5.00			50.00	S
	BUMPER CLIP 8x8,5	10.0 EA	8.20			82.00	S
	BUMPER RAIL REAR S90	1.0 EA	1621.60			1,621.60	S
	V031383527/BUMPER BR	1.0 EA	182.10			182.10	S

SERVICE ESTIMATE

34181 - C00001 SL: SERVICE SALES - PC

Mr Yang Shon Yu
15 Park Villas Green

Singapore 545437

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Yang Shon Yu

GST Reg.No:M28920628X
Inv.No. . . : B&P 0 Page 2
Inv.date. . : 31/10/2022
WIP No. . . : 47857
Veh.In/Out:
*Tel.No. . . : Mobile: 96933918
Reg.No. . . : SMQ3818U
Reg.date . . : 24/10/2019
Mileage .. : 0
Chassis No: LVYPS10ADLP078996

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	PARK SENSOR 29dB 90	1.0 EA	215.50			215.50	S

			Gross Total.	7,044.90
Labour Total	1,700.00		Net.....	7,044.90
Parts Total	5,344.90		GST @ 7.0%	493.14
Package Total	0.00		Total.....	7,538.05
			Paid.....	0.00
			Please Pay..	7,538.05

GST: S=StdRated; O=OutOfScope; Z=ZeroRated