

SERVICE ESTIMATE

34181 - C00001 SL: SERVICE SALES - PC

Mr Yang Shon Yu
15 Park Villas Green

Singapore 545437

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Yang Shon Yu

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1
Inv.date. : 31/10/2022
WIP No. . : 47857
Veh.In/Out:
*Tel.No. . : Mobile: 96933918
Reg.No. . : SMQ3818U
Reg.date . : 24/10/2019
Mileage ... : 0
Chassis No: LVYPS10ADLP078996

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLCE REAR BUMPER,REAR	0	350.00	0		350.00	S ✓
	LOWER SPOLIER,ETC						
800	TO PUTTY SPRAY PAINT ON REAR	0	750.00	0		750.00	S ✓
	BUMPER,ETC						
280	RENTAL CAR FOR 3 DAYS	0	600.00	0		600.00	S ?
	NOTES This Estimate Is Not Meant	0	0.00	0			S
	For Any Insurance Claim Purposes.						
	This Repair Will Take 3 Working Days.						
	NOTES Last 3 parts will be confirmed	0	0.00	0			S
	required replacement after we start						
	work on the car.						
	BUMPER COVER REAR S9 ✓ DE	1.0 EA	2753.90			2,753.90	S
	PROTECTING PLATE REA ✓ CUT	1.0 EA	439.80			439.80	S
	BLIND RIVET 4.0*21 P ✓ NEC	10.0 EA	5.00			50.00	S
	BUMPER CLIP 8x8,5 ✓ NEC	10.0 EA	8.20			82.00	S
	BUMPER RAIL REAR S90 ?	1.0 EA	1621.60			1,621.60	S
	V031383527/BUMPER BR ?	1.0 EA	182.10			182.10	S

SERVICE ESTIMATE

34181 - C00001 SL: SERVICE SALES - PC

Mr Yang Shon Yu
15 Park Villas Green

Singapore 545437

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Yang Shon Yu

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 31/10/2022

WIP No. . : 47857

Veh.In/Out:

*Tel.No. . : Mobile: 96933918

Reg.No. . : SMQ3818U

Reg.date . : 24/10/2019


Mileage .. : 0

Chassis No: LVYPS10ADLP078996

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	PARK SENSOR 29dB 90 ?	1.0 EA	215.50			215.50	S

3 Days

04/11/2022



Gross Total. 7,044.90

Labour Total 1,700.00
Parts Total 5,344.90
Package Total 0.00

Net..... 7,044.90
GST @ 7.0% 493.14
Total..... 7,538.05
Paid..... 0.00
Please Pay.. 7,538.05

GST: S=StdRated; O=OutOfScope; Z=ZeroRated