

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP SPF

Hui Rany

ESTIMATE

Vehicle No : SKP 9982 S

Make/Model : VOLKSWAGEN GOLF

Chassis No: WVWZZZAUZEW408677

Accident date : 03.11.2022

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

List Items

1	Rear exhaust chrome @ \$528.00 <i>Cat</i>	2	\$ 1,056.00 <i>300(SN)</i>
2	Rear exhaust pipe <i>new</i>	1	\$ 858.00 <i>+</i>
3	Rear LH lower arm <i>Bent.</i>	1	\$ 308.00 <i>✓</i>
4	Rear LH top arm <i>new</i>	1	\$ 264.00 <i>+</i>
5	Rear LH control arm @ \$275.00 <i>1 piece damaged</i>	2	\$ 550.00 <i>275.</i>
6	Rear bumper lower lip <i>cat new</i>	1	\$ 374.00 <i>+</i>
7	Rear LH wheel bearing <i>new</i>	1	\$ 462.00 <i>+</i>
			\$ 3,872.00
			Less 10% Disc \$ 387.20
			Total \$ 3,484.80

Labour Cost

1	To check wheel alignment <i>230</i>	\$ 100.00 <i>80.</i>
2	Remove & reinstall rear LH suspension	\$ 400.00 <i>150.</i>
Total		\$ 500.00
Grand Total		\$ 3,984.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1381.30

H/S: 1.1K

03 days

bluel: 1054.70

4/5 = 800 ✓