

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

TP Budget Direct.
Veron.

4-Nov-22

KNAF3416MK5036904

Our ref : TP/5185/22

Ang Kai Boon

RE : estimate cost for vehicle no : SMK 4708D

1 pc	bootlid <i>Dented</i>	\$	1,597.00	<i>1098.</i>
1 pc	bootlid lock <i>Dented</i>		112.00	—
1 pc	bootlid w/strip <i>lt</i>		100.00	—
1 pc	Cerato emblem <i>3 new</i>		28.00	—
1 pc	Kia emblem <i>7181</i>		32.00	—
2 pcs	bootlid reflector <i>lt</i>		1,216.00	<i>1058.</i>
1 pc	bootlid centre reflector <i>new</i>	<i>6462.90</i>	808.00	<i>x</i>
1 pc	bootlid trimboard <i>3 new</i>		202.00	<i>x</i>
10 pcs	bootlid trimboard clips <i>3 new</i>		40.00	<i>x.</i>
2 pcs	taillamp <i>lt</i>		1,350.00	—
1 pc	rear bumper <i>Dented</i>		888.00	<i>688.</i>
1 pc	rear bumper lower spoiler <i>Dented</i>		297.00	—
2 pcs	rear bumper signal lamp <i>RH Cured</i>		362.00	<i>181.</i>
2 pcs	rear bumper signal lamp covers <i>RH Cured</i>		80.00	<i>40</i>
1 pc	end panel <i>Dented</i>		674.00	—
1 pc	end panel inner garnish <i>Dented</i>		141.00	—
2 pcs	rear bumper retainers <i>new</i>		92.00	—
1 pc	rear bumper reinforcement <i>Cured</i>		418.00	—
2 pcs	rear bumper reinforcement brackets <i>Dented</i>		98.00	<i>130</i>
2 pcs	rear bumper brackets <i>Dented</i>		116.00	<i>50.</i>
4 pcs	rear bumper clips <i>new</i>		16.00	—
1 pc	key lock switch <i>Cured</i>		220.00	<i>165.</i>
1 pc	spare tyre cardboard <i>new torn</i>		311.00	<i>x</i>
2 pcs	rear fender inner trims <i>new RH torn</i>		400.00	<i>x</i>
1 pc	spare tyre panel <i>new</i>		819.00	<i>x</i>
1 pc	exhaust pipe <i>new</i>		757.00	<i>x</i>
1 pc	exhaust pipe heat shield <i>new</i>		136.00	<i>x.</i>
			11,310.00	
			less 10%	
			1,131.00	
			10,179.00	
1 pc	reverse sensor <i>Dented</i>		250.00	<i>snett</i>
1 pc	CC emblem <i>new</i>		20.00	<i>✓</i>
			10,449.00	

220

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : SMK 4708D

Bal brought forward:	\$	10,449.00
Panel beating.		1,500.00 1000
Spray painting.	2150	1,500.00 1000
Wiring.		30.00
Remove & refit exhaust pipe.		80.00 x.
Upholstery.		120.00 60
Rust proofing.		80.00 60
		13,759.00
	Plus 7% GST	963.13
		14,722.13

SD : Fourteen thousand seven hundred twenty-four & cents thirteen only.

Adrian Lj
1/s 07/11/22
of Days.
07
Total: 8832.50
L/s: 712

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: