



Section A - Accident Details

Registration Number	SHF178U
Case Reference Number	TAX/10/22/2096
Registration Date	1/12/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	HENG HWA KIAH
Type of Accident	Open Door Case
Accident Date and Time	30/10/2022 11:45 AM
Accident Reported Date and Time	31/10/2022 2:52 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116705
Special Instruction to ARC, if any	TP/LEFT REAR DOOR/TP
Prepared Date and Time	31/10/2022 3:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$936.00	\$450.00
Total Spare Part Cost	\$2,484.53	\$60.00
Total Other Cost	\$380.00	\$0.00
TOTAL COST	\$4,476.53	\$710.00 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / III
ARC / Surveyor Sign Off Date	07/11/2022 5:12 PM	07/11/2022 3:11 PM
Signature		
Remarks	PART BY PART / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0009	Invoice Number	
Quotation Date	06.12.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LH	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY DOOR HANDLE	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$936.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		67004-47211	PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1,401.70	100.00	\$0.00	Replace	Repair
		69210-47051-A1	DOOR OUTER HANDLE FRONT , LH	1.00	\$423.20	100.00	\$0.00	Replace	Repair
Total					\$3,292.70		\$60.00		

R
√ nec
R
R

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

60.00
+ 200.00
+ 450.00
710.00