



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co Reg No: 198063963G

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	XE3031E
Policy No:	DMCVSNW00058462201	Date of Loss:	31/10/2022
Vehicle Reg. No.:	XE3031E	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HIAP SENG TRANSPORT PTE LTD		
Driver:	ZHANG QIANGXIANG		
Make/Model:	MAN TGS 26.400, 10.5 D 6X4 BBS (M)	Vehicle Reg. Date:	06/06/2017
Vehicle Colour:	White	Chassis No:	WMA26SZZ9HM742151
Engine No:	50547181714720		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)		

COST OF CLAIMS

	Amount
Parts	7,654.49
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	7,654.49
+ GST 7.00% (\$)	535.81
Nett Amount (\$)	8,190.30
+ Previous Estimates (\$)	36,580.56
Claim Total (\$)	44,770.86

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Nov 2022)

Parts: N/A MAN TGS 26.400 10.5 D 6X4 BBS (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Goldbell Engineering Pte Ltd/XE3031E/08/11/2022 23:21

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*DOOR WINDOW LEFT	0.00	0.00	-
2	1		*WIND-DOWN WINDOW LEFT TINTED ? X nn	0.00	0.00	*615.60 F
3	2		*MOUNTING DOOR GLASS ? X nn	0.00	0.00	*45.48 F
4	2		*CLAMPING FRAME ? X nn	0.00	0.00	*12.78 F
5	2		*PAN-HEAD SCREW ? X nn	0.00	0.00	*8.22 F
6	1		*WINDOW GUIDE REPLACEMENT ? X nn	0.00	0.00	*282.73 F
7	1		*DOOR LEFT SHELL	0.00	0.00	-
8	1		*DOOR LEFT ✓ DD	0.00	0.00	*3,927.82 F ✓
9	1		*DOOR HINGE LEFT, UPPER ? X nn	0.00	0.00	*690.16 F
10	1		*RUBBER PAD ELASTOMER ✓ NEC	0.00	0.00	*9.63 F ✓
11	1		*TAPPET ✓ NEC	0.00	0.00	*5.40 F ✓
12	1		*LOCKER WASHER ✓ NEC	0.00	0.00	*6.30 F ✓
13	1		*DOOR HINGE LEFT, LOWER ? X nn	0.00	0.00	*369.40 F
14	1		*HINGE PIN ✓ NEC	0.00	0.00	*16.11 F ✓
15	1		*DAMPING PLATE ? X nn	0.00	0.00	*73.48 F
16	1		*CURB MIRROR ELECTRICALLY ACTUATED	0.00	0.00	-
17	1		*CURB MIRROR CO-DRIVERS SIDE ELECTRIC ✓ BR	0.00	0.00	*1,220.26 F ✓
18	1		*MIRROR GLASS HEATABLE ✓ BR	0.00	0.00	*329.94 F ✓
19	2		*CYLINDER SCREW ✓ NEC	0.00	0.00	24.37 ✓ *24.38 F
20	1		*GROMMET WITH HOLE ✓ NEC	0.00	0.00	*16.80 F ✓

F=Franchise part.

Total Parts (S\$) 7,654.49

Goldbell Engineering Pte Ltd/XE3031E/08/11/2022 23:21. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Steve (LKK)
09/11/22

5556.63

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 05 Apr 2023)

Parts: N/A MAN TGS 26 400 10.5 D 6X4 BBS (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Goldbell Engineering Pte Ltd/XE3031E/05/04/2023 11:36

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Dopr	Amount
1	1		*COVERING C.R.C. ✓	0.00	0.00	*93.27 F ✓
Total Parts (\$\$)						93.27

F=Franchise part

Goldbell Engineering Pte Ltd/XE3031E/05/04/2023 11:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Akid LKK

06104123 1540



GOLDBELL
ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 6 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3876
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No. 190000630

(SUPPLEMENTARY)

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	XE3031E
Policy No:	DMCVSNW00058462201	Date of Loss:	31/10/2022
Vehicle Reg. No.:	XE3031E	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HIAP SENG TRANSPORT PTE LTD		
Driver:	ZHANG QIANGXIANG		
Make/Model:	MAN TGS 26.400, 10.5 D 6X4 BBS (M)	Vehicle Reg. Date:	06/06/2017
Vehicle Colour:	White		
Engine No:	50547181714720	Chassis No:	WMA26SZZ9HM742151
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)		

COST OF CLAIMS

	Amount
Parts	1,879.08
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	1,879.08
+ GST 7.00% (\$)	131.54
Nett Amount (\$)	2,010.62
+ Previous Estimates (\$)	44,870.66
Claim Total (\$)	46,881.28

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Apr 2023)

Parts: N/A MAN TGS 26.400 10.5 D 6X4 BBS (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Goldbell Engineering Pte Ltd/XE3031E/13/04/2023 10:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*DOOR CONTROL MODULE, RH Malfunction	0.00	0.00	*1,879.08 F ✓
Total Parts (\$)						1,879.08

F=Franchise part.

Goldbell Engineering Pte Ltd/XE3031E/13/04/2023 10:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

09/05/23 - LKK