

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 09 Nov 2022

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|----------------------|
| Vehicle No | : XE3031E | Accident Date | : 31/10/2022 |
| Make | : MAN TGS 26.400 | Policy No. | : DMCVSNW00058462201 |
| Assignment Date | : 07/11/2022 | Excess | : S\$2,000.00 |
| Date of Inspection | : 07/11/2022 | Est. Duration of Repair | : 7 |
| Inspection At | : GOLDBELL ENGINEERING PTE LTD (TUAS) 10 TUAS AVE 18 SINGAPORE 638894 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 41,841.93 |
| Revised Amount | :S\$ | 25,931.40 |
| Check Items (Estimated) | :S\$ | 2,575.78 |
| Total | :S\$ | 28,507.18 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|------------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 120,000.00 |
| COE / PARF Rebate | :S\$ | 11,917.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 108,083.00 |

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.