

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Senthilan Dillen Selvarajoo

Date: 09 Nov 2022

Preliminary Advice

Vehicle No	: SLT6777E	Accident Date	: 26/10/2022
Make	: MERCEDES-BENZ GLC 250	Policy No.	: DMPG21014585
Assignment Date	: 07/11/2022	Excess	: S\$700.00
Date of Inspection	: 09/11/2022	Est. Duration of Repair	: 4
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01, KAKI BUKIT (SOUTH WING) SINGAPORE 415933		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,992.60
Revised Amount	:S\$	4,791.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,791.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	64,798.00
Salvage Value	:S\$	

Margin for Repair

:S\$ 75,202.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : The vehicle repair on part by part basis due to no 2nd hand parts available.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.