

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 08 Nov 2022

Preliminary Advice

Vehicle No	: SMF2328G	Accident Date	: 03/11/2022
Make	: TOYOTA HARRIER	Policy No.	: SP2002536015-01
Assignment Date	: 04/11/2022	Excess	: S\$500.00
Date of Inspection	: -	Est. Duration of Repair	: 7
Inspection At	: -		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,712.80
Revised Amount	:S\$	9,110.30
Check Items (Estimated)	:S\$	4,794.00
Total	:S\$	13,904.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	44,773.00
Salvage Value	:S\$	
Margin for Repair	:S\$	75,227.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by part repair as there is no 2nd hand parts available.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .