

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Nov 2022)

Parts: M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SMF2328G/04/11/2022 17:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet	0.00	0.00	*440.00 F bt ✓
2	1		*Bonnet Chrome	0.00	0.00	*180.00 F ?
3	8		*Bonnet Insulator Clip	0	0.00	*16.00 FS x
4	2		*Bonnet Hinge	0.00	0.00	*100.00 F x
5	1		*Radiator Grille Assy	0.00	0.00	*360.00 F x
6	1		*RH Headlamp (HID)	0.00	0.00	*2,150.00 F cur ✓
7	1		*RH Headlamp Bracket	0.00	0.00	*45.00 F ?
8	1		*Front Bumper	0.00	0.00	*290.00 F de ✓
9	10		*Front Bumper Clip	0	0.00	*20.00 FS ne ✓
10	1		*LH Front Bumper Side Retainer	0.00	0.00	*50.00 F x
11	1		*RH Front Bumper Side Retainer	0.00	0.00	*50.00 F de ✓
12	1		*Front Bumper Lower Grille	0.00	0.00	160 *170.00 F ?
13	1		*Front Bumper Sponge - Centre	0.00	0.00	*75.00 F ?
14	1		*Front Bumper Sponge - RH	0.00	0.00	*45.00 F de ✓
15	1		*Front Bumper Lower Lip	0.00	0.00	*165.00 F int ✓
16	1		*Front Bumper Parking Sensor - RH Outer	0.00	0.00	*185.00 F R ✓
17	1		*Front Bumper Parking Sensor Holder - RH Outer	0.00	0.00	*28.00 F ne ✓
18	1		*Front Bumper Running Lamp - RH	0.00	0.00	*380.00 F cur ✓
19	1		*RH Fog Lamp	0.00	0.00	*145.00 F ?
20	1		*Front Support Panel	0.00	0.00	*400.00 F ?
21	1		*RH Front Fender	0.00	0.00	*335.00 F bt ✓
22	1		*RH Front Fender Shield	0.00	0.00	*175.00 F de ✓
23	10		*RH Front Fender Shield Clip	0	0.00	*20.00 FS ne ✓
24	1		*RH Wing Mirror Cover	0.00	0.00	*65.00 F R ✓
25	1		*Wiper Washer Tank	0.00	0.00	*85.00 F de ✓
26	1		*Wiper Washer Tank Neck	0.00	0.00	*55.00 F ?
27	1		*RH Front Tyre - Dunlop 235/55R18	0	0.00	*340.00 FS ?
28	1		*RH Front Rim - 18	0	0.00	*1,150.00 FS id ✓
29	1		*RH Front Shock Absorber	0.00	0.00	*350.00 F bt ✓
30	1		*RH Front Shock Absorber Bearing	0.00	0.00	*25.00 F ne ✓
31	1		*RH Front Shock Absorber Mounting	0.00	0.00	*85.00 F ne ✓
32	1		*RH Front Knuckle Arm	0.00	0.00	*225.00 F bt ✓
33	1		*RH Front Lower Arm	0.00	0.00	*210.00 F bt ✓
34	1		*RH Front Linkage	0.00	0.00	*60.00 F ?
35	1		*Front Axle	0.00	0.00	*1,180.00 F ?
36	1		*Steering Rack	0.00	0.00	*780.00 F ?
37	1		*Tie Rod End	0.00	0.00	*50.00 F ?
38	1		*RH Front Wheel Hub w/Bearing	0.00	0.00	*250.00 F bt ✓

F=Franchise part, S=SpecNet.

ifc ball joint	80.00		
		Sub Total (\$\$)	10,734.00
		+ Margin on L,N Items 10.00% (\$\$)	918.80
		Total Parts (\$\$)	11,652.80

Falcon-Air Auto Services Pte Ltd/SMF2328G/04/11/2022 17:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

* RH Headlamp Module - 390
 * LH Fender inner seal - 40
 * RH side panel/beam - 70
 * RH front fender bracket - 74

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To check wiring and focus headlamp	New	80.00 40
2	To remove/replace undercarriage and front axle	New	350.00 150
3	To install steering rack and reprogramming	New	350.00 150
4	Chassis alignment	New	300.00 200?
5	Computerise wheel alignment	New	120.00 80
6	To transfer new tyre to new rim and balancing	New	60.00 30
7	To remove/replace necessary parts, repair RH front fender inner panel, cut out accident damage parts, reweld new panel, alignment	New	1,000.00 750
8	To spray paint bonnet, front bumper, headlamp panel, RH front fender, fender inner panel, RH front door, RH wing mirror cover	New	1,800.00 1000
Gross Labour Cost (\$\$)			4,060.00

Falcon-Air Auto Services Pte Ltd/SMF2328G/04/11/2022 17:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

[a subsidiary of Falcon-Air Holdings Pte Ltd]

Head Office : Bk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Bk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

Tanfiki 97495749
Not an invoice 7/4/22
EX500
P/P Resurvey before paint.
tanfiki@lkkauto.com
6 days - 07 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: