



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400067W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SLW3439K\*RA

EQ INSURANCE COMPANY LIMITED  
MOTOR CLAIM DEPARTMENT  
5 MAXWELL ROAD #17-00  
TOWER BLOCK, MND COMPLEX  
SINGAPORE 069110  
62239433

### Vehicle & Document Information

WIP No **60735**  
Reg No/Reg Date **SLW3439K\*RA / 08/02/2018**  
Date In/Mileage **WDD2462422J468300**  
Chassis No **27091031515793**  
Engine No **MB/B 180 SEDAN (W246) \*STYLE**  
Make/Model **027 787 Mountain Gr/ 041 111 ARTICO Leat**  
Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator
ME000058	Credit	03/11/2022 / 18:41	CH	371 / Go Chee Han

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
---------------------------------	--	-----	------------	-------	--------

# THIS IS NOT AN OFFICIAL TAX INVOICE

Z REQUEST  
Customer Request  
M BPN SUN  
POLICY NO/ACC DATE : 5130085572 // 2-11-2022  
DRIVE IN/TP VEH NUMBER : 3-11-2022 // SLJ88C - EQ  
DATE IN/DATE SURVEY:  
DIRECT SETTLEMENT BY:

A	BPILAB	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.			<del>3800</del> 5700.00
A	BPIRES	RESPRAY RH/REAR DOOR & RH/REAR FENDER & RH/RUNNING BOARD & REAR BUMPER			<del>2800</del> 2800.00
A	BPILAB	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT		0.01	<del>3200.00</del> 3200.00
A	BPILAB	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT		0.10	<del>380.00</del> 380.00
A	BPILAB	REPLACE RIGHT REAR DOOR, TRANSFER COMPONENT PARTS			<del>120.00</del> 120.00
A	BPILAB	REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.			<del>480.00</del> 480.00
A	BPILAB	TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT			<del>960</del> 1400.00
S	BPN SUB	LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT)			<del>540.00</del> 540.00
A	97250001	WHEEL BALANCE AND INSTALL NEW VALVE HEAD			<del>60.00</del> 60.00
M	RH/REAR DOOR	CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM RH/REAR DOOR	1.00	2069.15	00.00
M	RH/REAR DOOR SEAL	RH/REAR DOOR SEAL	1.00	313.32	00.00
M	RH/REAR ABSORBING DOOR	RH/REAR ABSORBING DOOR	1.00	74.42	00.00
M	RH/REAR DOOR DOWEL	RH/REAR DOOR DOWEL	6.00	3.77	00.00

Confirmed & accepted by

Go Chee Han  
DID : 6771 4336 HP : 9181 7717  
Email : cheehan.go@gocheecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Center Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SLW3439K\*RA

EQ INSURANCE COMPANY LIMITED  
MOTOR CLAIM DEPARTMENT  
5 MAXWELL ROAD #17-00  
TOWER BLOCK, MND COMPLEX  
SINGAPORE 069110  
62239433

### Vehicle & Document Information

WIP No **60735**  
Reg No/Reg Date **SLW3439K\*RA / 08/02/2018**  
Date In/Mileage **WDD2462422J468300**  
Chassis No **SLW3439K\*RA**  
Engine No **27091031515793**  
Make/Model **MB/B 180 SEDAN (W246) \*STYLE**  
Colour/Trim **027 787 Mountain Gr/ 041 111 ARTICO Leat**

Account No **WE000058** Terms **Credit** Date/Time Printed **03/11/2022/ 18:41** CSE **CH** Operator **371 / Go Chee Han**

### Description of Goods / Services

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
M					10.00	2.70	00.00	27.00
M					1.00	280.59	00.00	280.59
M					1.00	2702.14	00.00	2702.14
M					1.00	582.12	00.00	582.12
M					1.00	394.69	00.00	394.69
M					1.00	116.04	00.00	116.04

BLIND RIVET WITH PAN HEAD  
FOOTPLATE  
RH/REAR FENDER  
RH/REAR DISK WHEEL SC  
RH/RUNNING BOARD  
CAVITY PRESERVATIVE

*Rene*  
*He goes to*  
*8 days*  
*30/11/22 @ 16:30*  
*Resy before part*

**NOT AN OFFICIAL AXIOM**

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Go Chee Han**  
DID : 6771 4336 HP : 9181 7717  
Email : cheehan.go@cyclcarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Centre - Pandan Loop

Confirmed & accepted by \_\_\_\_\_  
Authorized signatory and company stamp

7% GST on **18742.09**      **1311.95**  
Total Payable **20,054.04**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.