



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW3439K*RA

Finalization

Vehicle & Document Information

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT
5 MAXWELL ROAD #17-00
TOWER BLOCK, MND COMPLEX
SINGAPORE 069110
62239433

WIP No 60735
Reg No/Reg Date SLW3439K*RA / 08/02/2018
Date In/Mileage 30/11/2022/ 38345
Chassis No WDD2462422J468300
Engine No 27091031515793
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 027 787 Mountain Gr/ 041 111 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WE000058	Credit	10/01/2023/ 19:16	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M-BPNSUN POLICY NO/ACC DATE : 5130085572 // 2-11-2022 DRIVE IN/TP VEH NUMBER : 3-11-2022 // SLJ88C - EQ DATE IN/DATE SURVEY: 30-11-2022@1630 // RASUL - LKK DIRECT SETTLEMENT BY: 25-11-2022@0915 // JOSEPHINE - EQ				3840.00
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.			0.02	2800.00
A BPIRES RESPRAY RH/REAR DOOR & RH/REAR FENDER & RH/RUNNING BOARD & REAR BUMPER			0.10	380.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				120.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				480.00
A BPILAB REPLACE RIGHT REAR DOOR, TRANSFER COMPONENT PARTS				960.00
A BPILAB REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.				540.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				60.00
S BPNSUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM,(RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD				180.00
A 97250001 CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM	1.00	2069.15	00.00	2069.15
X RH/REAR DOOR	1.00	313.32	00.00	313.32
X RH/REAR DOOR SEAL	1.00	74.42	00.00	74.42
X RH/REAR ABSORBING DOOR	6.00	3.77	00.00	22.62
X RH/REAR DOOR DOWEL				

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW3439K*RA

Finalization

EQ INSURANCE COMPANY LIMITED
MOTOR CLAIM DEPARTMENT
5 MAXWELL ROAD #17-00
TOWER BLOCK, MND COMPLEX
SINGAPORE 069110
62239433

Vehicle & Document Information
WIP No 60735
Reg No/Reg Date SLW3439K*RA / 08/02/2018
Date In/Mileage 30/11/2022/ 38345
Chassis No WDD2462422J468300
Engine No 27091031515793
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 027 787 Mountain Gr/ 041 111 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WE000058	Credit	10/01/2023/ 19:16	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BLIND RIVET WITH PAN HEAD	10.00	2.70	00.00	27.00
X FOOTPLATE	1.00	280.59	00.00	280.59
X RH/REAR FENDER	1.00	2702.14	00.00	2702.14
R RH/REAR DISK WHEEL	1.00	582.12	00.00	582.12
X CAVITY PRESERVATIVE	1.00	116.04	00.00	116.04

ESTIMATE

Confirmed & accepted by

Nett	15,547.40
8% GST on	1243.79
Total Payable	16,791.19

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg