

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011079/AVP3Q2
Date: 03/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00014362101
Claimant Vehicle No :	SKQ6060S	Insured Vehicle No :	SKW9486X
Date of Loss:	03/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D207940/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ6060S	Engine No:	DEM028155
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF44MA021815
Reg. Date:	29/06/2021 (Man. Year: 2020)	Odometer:	9485 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,401.00	3,452.00	4,949.00	58.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,432.00	1,952.00	2,480.00	55.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,833.00	5,404.00	7,429.00	57.89
+ GST 8.00/8.00% (S\$)	1,026.64	432.32	594.32	57.89
Nett Amount (S\$)	13,859.64	5,836.32	8,023.32	57.89

INSPECTION

Date of Assignment:	04/11/2022		
Date Inspected:	10/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2023)
Parts: 143	AUDI A4 2.0 TFSI S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ6060S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,493.00 FS	*2,493.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	173.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP -LOWER	Not Necessary	125.00 FS	*- FS
4	1		*REAR BUMPER SECURING STRIP -UPPER	Not Necessary	249.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Deformed	276.00 FS	*276.00 FS
6	1		*REAR BUMPER BRACKET -RH	Damaged	228.00 FS	*227.50 FS
7	1		*REAR BUMPER REFLECTOR -LH/RH	O/S Cracked	96.00 FS	*47.80 FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,131.00 FS	*- FS
9	2		*REAR BUMPER IMPACT BAR GASKET -LH/RH	Not Necessary	32.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION -RH UPPER	Not Necessary	51.00 FS	*- FS
11	1		*REAR BUMPER GUIDE SECTION -LH/RH LOWER	N/S Cracked	52.00 FS	*25.20 FS
12	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	188.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	531.00 FS	*- FS
14	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
15	1		*EXHAUST TAIL PIPE TRIM -RH	Cut	383.00 FS	*382.50 FS
16	1		*REAR BOOT LID OPENING CONTROL UNIT	Not Necessary	484.00 FS	*- FS
17	1		*REAR TAILGATE OPENING SENSOR LINE	Not Necessary	228.00 FS	*- FS
18	1		*EXHAUST SILENCER -RH	Not Necessary	1,226.00 FS	*- FS
19	1		*EXHAUST SILENCER BRACKET	Not Necessary	45.00 FS	*- FS
20	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,401.00	3,452.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER ,TO REPAIR REAR END PANELLING RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,400.00	700.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING	New	2,000.00	700.00
4	TO RENEW RHS REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,432.00	1,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >