



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA		Ref: CC4/ASM22011084/Upa3q2 Date: 15/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8287B	Veh. Inspected	SNG 5667R
Policy No.	P2465714	Coverage (\$)	0.00
Claim No.	S2M04DQ7	Excess (\$)	0.00
Assign From		Assign Date	07/11/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	GK82102531	Colour	SILVER
Odometer	20674 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/10/2022	Inspection Date	07/11/2022
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	