



AVERMENT AUTO PTE LTD

8 Kaki Bukit Ave 4 #07-16 Premier@Kaki Bukit S(415875)
Co. Reg No : 2022227522G

DATE : 03 OCT 2022

OWNER PARTICULAR

OWNER ID : SXXXX869J

TO : CHINA TAIPING (SMW2365J)
ATTENTION : MOTOR CLAIMS DEPARTMENT
JOB TYPE : T/P CLAIMS

Xiao Chen.

VEHICLE DETAILS

VEHICLE NO. : SKP6396D
MODEL / MAKE : BMW 316i
CHASSIS NO : WBA3A12000J722167

ACCIDENT DETAIL

DATE & TIME OF ACCIDENT : 26 OCT 2022 @ 00:00HRS

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

PERSON INCHARGE :
MR. WINSON NG 91866680

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Replaced</i>	1	\$ 1,420.00	\$ 1,420.00
2	REAR BUMPER SIDE RETAINER RH <i>me</i>	1	\$ 65.00	\$ 65.00
3	REAR BUMPER CORNER RETAINER RH <i>me</i>	1	\$ 13.00	\$ 13.00
4	REAR FENDER RH <i>Repair</i>	1	\$ 2,010.00	\$ 2,010.00
5	REAR FENDER INNER SHIELD RH <i>me</i>	1	\$ 856.00	\$ 856.00
6	REAR SUSPENSION KNUCKLE ARM RH <i>me</i>	1	\$ 1,350.00	\$ 1,350.00
7	REAR SUSPENSION KNUCKLE ARM BEARING RH <i>me</i>	1	\$ 212.00	\$ 212.00
8	REAR SUSPENSION LOWER ARM RH <i>me</i>	1	\$ 156.00	\$ 156.00
9	REAR SUSPENSION TRAILING ARM RH <i>me</i>	1	\$ 140.00	\$ 140.00
10	REAR SUSPENSION THRUST ARM RH <i>me</i>	1	\$ 390.00	\$ 390.00
11	REAR SUSPENSION TORSIN ARM RH <i>me</i>	1	\$ 335.00	\$ 335.00

TOTAL PRICE \$ 6,947.00
LESS -5% \$ (347.35)
SUB TOTAL PRICE \$ 6,599.65

1485

1410.75

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS SET <i>me</i>	1	\$ 100.00	\$ 100.00
2	REAR FENDER SEALANT RH <i>me</i>	1	\$ 120.00	\$ 120.00
3	REAR FENDER INNER SHIELD CLIPSS SET RH <i>me</i>	1	\$ 80.00	\$ 80.00
4	REAR SPORT RIM RH <i>me</i>	1	\$ 1,080.00	\$ 1,080.00
5	REAR TYRE RH <i>me</i>	1	\$ 680.00	\$ 680.00

1010

TOTAL

\$ 2,060.00

QUOTATION SUMMARY PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

1 TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 800 1,500.00
2 TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 20 1,000.00
3 TO APPLY ANTI-RUST & TUFF KOTE	\$ 40 150.00
4 TO PERFORM LIGHTING & WIRING CHECK	\$ 30 250.00
5 TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ X 580.00
6 TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ X 220.00
7 TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 50 230.00
8 TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	\$ 120 X 480.00
9 TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 80 240.00
10 TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ X 220.00
11 TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 120 550.00
12 TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 1320 + 200.00

TOTAL \$ 5,620.00

Adrian G
h/s 08/11/22
OBS Reps

16

QUOTATION SUMMARY PAGE 05

ESTIMATE REPORT

TOTAL PARTS COST :	\$	8,659.65
TOTAL LABOUR COST :	\$	5,620.00
TOTAL REPAIR COST :	\$	14,279.65

APPROVED DETAILS

NO. OF REPAIR DAYS :

REPAIR UNDER : **PART BY PART** OR **LUMPSUM**

DATE / TIME OF SURVEY :

SURVEYED BY / FROM :

CONTACT NUMBER :

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

EXCESS :

PARTS :
NETT ITEMS :
LABOUR :
TOTAL :
L/S -20% :
SUB TOTAL :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian

L/S 07/11/22

OSRyp

total: 3740.75

L/S: 3K

3K.