

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011090/RQP3M4**Date:** 13/03/2023**REFERENCE**

Insured/Claimant: CHNG HONG SHENG Policy No: DMPCNA00164792202

Date of Loss: 02/11/2022

Nature of Claim: OD

Claim No: SNM22D207880/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SML4035G**

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A)

Engine No: R16B25501149

Reg. Date: 19/07/2018 (Man. Year: 2018)

Chassis No: MRHFC5650JT001002

Colour: Grey

Odometer: 79010 km

Engine Capacity: 1597 cc

Market Value/New Car Price: S\$85,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,115.00	2,005.00	-890.00	-79.82
Miscellaneous Items	310.00	60.00	250.00	80.65
Labour	306.60	285.60	21.00	6.85
Paintwork Labour	323.85	465.03	-141.18	-43.59
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,055.45	2,815.63	-760.18	-36.98
+ GST 7.00/7.00% (S\$)	143.88	197.09	-53.21	-36.98
Nett Amount (S\$)	2,199.33	3,012.72	-813.39	-36.98

INSPECTION

Date of Assignment: 07/11/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Date Inspected: 08/11/2022 Inspected At: AUTO INSURE PTE LTD

6 MARSILING LANE

SINGAPORE 739145

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2023)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML4035G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		1,115.00 F	*2,005.00 F
			Total Parts (\$\$)		1,115.00	2,005.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	310.00	60.00
Sub Total (\$\$)			310.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	323.85	465.03
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	306.60	285.60
Gross Labour Cost (\$\$)			630.45	750.63

Report was unsubmitted during this print-out.

< END OF ESTIMATES >