



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATN: ANG YVONNE		Ref: CS/ASM22011092/Avp3e2 Date: 01/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMF 8259H	Veh. Inspected	GBE 9990H
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04E5Z	Excess (\$)	0.00
Assign From	ANG YVONNE	Assign Date	07/11/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE DX	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KDH2010189858	Colour	SILVER
Odometer	113845 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	HABILEAD	6 mm
L/H Front Tyre	195 R15C	HABILEAD	6 mm
R/H Rear Tyre	195 R15C	HABILEAD	6 mm
L/H Rear Tyre	195 R15C	HABILEAD	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/10/2022	Inspection Date	08/11/2022
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	