

FBD8397H. 2009 Augnt.

2.4k

Yamaha YZF 150 CC

TP Budget Direct.
Xiao Chen.

ME120P01192019840.

Rees Number Plate.	Best	25 (SN)	✓
Rees Mudflap.	Dehd	68.	✓
Taillamp.	cracked	115	✓
Rees RH Signal Lamp.	Crackd	34.	✓
Rees Exhaust Pipe.	Best	490	✓
Rees Exhaust Pipe Heat Shield.	cut	110.	✓
Rees Exhaust Pipe End Protector.	Crackd	H5.	✓
Rees RH Footrest.	cut	35	✓
Rees RH Footrest Bracket.	Best	108	✓
Rees RH Side Fairing.	Rejis	120.	+
Rees Fairing Handle.	or mr	60	+
Centre Fairing (lower) RH.	Rejis	78	+
Front RH Footrest.	ut	35	✓

FB D8397H.

Engine Cover	ut	85	/
Front Fairing (RH)	ut	185	/
<u> </u>		<u> </u>	/
Front RH Signal Lamp	ut	42	
Balancer RH.	ut	28	/
Handle Bar RH.	Best	55	/
Front RH Wing Mirror.	ut	45	/
Front RH Lever	ut	40	/
Headlamp.	Al m	285	x
Headlamp Cowling.	ut	155	/
Front Fender	Ris	70	+
Front Fork Assy	Ris	480.	+
Steering Under Bracket.	Al m	160	+
Steering Case and Bearing.	Nov	55	/

FBD8397H.

Front Fork Oil ~~new~~ 40(SN) ✓

Rear BOX ~~lt~~ ~~280(SN)~~ 250(SN)

Rear Box Bracket. ~~Best~~ ~~200(SN)~~ 200(SN)

Rear Swing Arm. ~~Best~~ 310. ✓

Stickers ~~new~~ 100 50(SN)

Labour ~~400~~ 200

Spray Painting ~~400~~ 200

Wiring. ~~50~~ 30

To straighten body chassis ~~280~~ 200

Towing Fees. 40. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Witnessed by Repairer

List 2040

Len 10%: 1836

S.N: 525

Labour: 670

total: 2031

L/S: 2.HK. 04 Dec