

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 17 Feb 2023

**Preliminary Advice**

Insured Vehicle No	: SND7658U	Accident Date	: 03/11/2022
TP Vehicle No	: SDV1221J	Assignment Date	: 10/11/2022
Make	: MERCEDES-BENZ S300L	Est. Duration of Repair	: 6
Date of Inspection	: 07/11/2022		
Inspection At	: AUTOBACS CAR CARE ( SINGAPORE) PTE LTD (HQ) 8 KAKI BUKIT AVE 4,, #08-45/46 PREMIER@KAKI BUKIT, SINGAPORE 415875		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,989.79
Revised Amount	:S\$	7,838.82
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,838.82
Lump Sum Repair	:S\$	6,250.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.