



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI22011102/Kny3e2

Date: 22/11/2022

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBS 6468X	Veh. Inspected	SKK 4652D
Policy No.	D-1909411MFB	Coverage (\$)	0.00
Claim No.	D22003240MFBP	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	07/11/2022

2. Vehicle Particulars & Condition

Make & Model	AUDI Q5 (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WAUZZZ8R8DA101370	Colour	METALLIC BLACK
Odometer	65220 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R19	PIRELLI	7 mm
L/H Front Tyre	235/55 R19	PIRELLI	7 mm
R/H Rear Tyre	235/55 R19	PIRELLI	7 mm
L/H Rear Tyre	235/55 R19	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/10/2022	Inspection Date	10/11/2022
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**