

SLN1338D.

Honda Shuttle

GK81007118

TPAXA.

Veron.

JEC

Rees	Number Plate	2	30(SN)	✓
Rees	Number Plate Holder	mm	30(SN)	✓
Rees	Bumper	Distorted	885	✓
Rees	Bumper Clips.	mm	30(SN)	✓
Rees	Bumper Side Holder	x02	32 x 2 = 64.	✓
Rees	Bumper Side Sponge	x02 RH	47 x 2 = 94	47
Rees	Bumper Side Grille	x02 mm	68 x 2 = 136.	✓
Rees	Bumper Side Grille Reflector	x02 RH	49 x 2 = 98	49.
Rees	Bumper Tow Cover	Deformed	32	✓
Reverser	Sensor	mm	280(SN)	100(SN)
Rees	End Panel	Dented	681	✓
Rees	End Panel Top Garnish	mm	185	✓
Rees	End Panel Top Garnish Clips.	mm	20(SN)	✓
Rees	End Panel Sealant.	mm	60(SN)	✓
Rees	End Panel Inner			

SLN 1338D

Taillep x 22	RH cut	520 x 2 = 1040	SW
Tailamp Panel RH	Dented	272	✓
Tailgate	Distorted	1185	✓
Tailgate Lock	Bent	188	✓
		209	✓
Tailgate Weatherstripe	cut		
Tailgate Reflector x 22	RH cut	395 x 2 = 790	395
Tailgate Inner Trim Board	cracked	325	✓
Tailgate Inner Trim Board clips	cr	30(SN)	✓
Tailgate Outer Garnish	cr	384	x
Tailgate Outer Garnish clips	cr	20(SN)	x
Tailgate Glass Moulding	cr	162	✓
Tailgate Glass Sealant	cr	60(SN)	✓
Honda Logo	cr	45	x
Shuttle Wordings	cr	48	✓
Rees RH Fender	cr	1011	x
Rees RH Fender Glass Moulding	cr	98	x

SLN 1338D.

Reer RH Fender Gloss Sealant.

MM 40(SN) X

RH and 359

Reer Fender Inner Trim Board x02

~~399~~ x 2 = 798

Reer Fender Inner Trim Board Clips

MM 60(SN) 50(SN)

Spere Tyre Panel

Reer's

1188 X

Spere Tyre Panel Top Board.

Deformed

585 ✓

Utility Tray.

MM MM

495 X

Reer Exhaust Pipe.

745 X

Reer Exhaust Pipe Manting.

35 X

Reer Exhaust Pipe Gasket.

MM

32 X

Reer Exhaust Pipe Heat Shield

MM

78 X

Reer Camera.

80(SN) X

Jack Cover

Deformed

145 ✓

4681

6496

S.N. 430

519680

SLN 1338D.

Panel Beating

Spray Painting.

Wiring.

To remove cruise sensor

To remove rear camera.

To remove upholstery, and reseat.

To spray tint out.

To transfer tailgate battery.

To remove tailgate g/s

To remove rear fender g/s

To remove exhaust pipe.

To remove fuel tank

~~1800~~ 1200

~~1600~~ 1100

~~50~~ 30

~~100~~ 50

~~100~~ 50

~~300~~ 60

~~150~~ 80

~~150~~ 80

~~180~~ 120

120 +

150 +

~~150~~ + 2770

4850

18,143

Total: 8396.80

L/S 6.7K.

07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: