

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	<b>Document No.</b>	: SQT22003231	<b>Page</b>	1
<b>Registration No</b>	: SGE8254Y	<b>Date</b>	: 3. Nov 2022		
<b>Chassis No</b>	: JHMRV3800NS202567	<b>Customer No.</b>	: WZL009		
<b>Model</b>	: HRV DX-SIN CVT YM 2022	<b>Svc Advisor</b>	: NG SIN HAI		
<b>Owner's Name</b>	: LEONG YEW KAY	<b>Engine No</b>	: L15ZK1102567		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 3. Nov 2022 3:11:30 PM		
<b>Date of Accident</b>	: 3/11/2022	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
04715-3M0-000ZZ	FACE,RR.BUMPER	1	555.30	25	416.47	29.15	445.62
33505-TL0-G01	REAR RR ASSY,R	1	49.00	25	36.75	2.57	39.32
33555-TL0-G01	REAR RR ASSY,L	1	49.00	25	36.75	2.57	39.32
71630-3M0-003	SPACER,R.RR.BPR S	1	16.40	25	12.30	0.86	13.16
71680-3M0-003	SPACER,L.RR.BPR S	1	16.40	25	12.30	0.86	13.16
91505-TM8-003	CLIP,BUMPER	6	2.30	25	10.35	0.72	11.07
33500-3M0-J01	LIGHT ASSY,R.TAIL	1	378.80	25	284.10	19.89	303.99
				<b>Sum Item</b>	<b>809.02</b>	<b>56.62</b>	<b>865.64</b>
BOSUN	SUNDRIES	1	110.00		110.00	7.70	117.70
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		250.00	17.50	267.50
BKRP21B	CUT OFF & RENEW RR FLOOR PANEL, REPAIR LH FRAME	1	1200.00		1200.00	84.00	1284.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1200.00		1200.00	84.00	1284.00
				<b>Sum Labor</b>	<b>3010.00</b>	<b>210.70</b>	<b>3,220.70</b>

Survey By

Printed on 3/11/2022 3:24:07 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	<b>Document No.</b>	: SQT22003231	<b>Page</b>	2
<b>Registration No</b>	: SGE8254Y	<b>Date</b>	: 3. Nov 2022		
<b>Chassis No</b>	: JHMRV3800NS202567	<b>Customer No.</b>	: WZL009		
<b>Model</b>	: HRV DX-SIN CVT YM 2022	<b>Svc Advisor</b>	: NG SIN HAI		
<b>Owner's Name</b>	: LEONG YEW KAY	<b>Engine No</b>	: L15ZK1102567		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 3. Nov 2022 3:11:30 PM		
<b>Date of Accident</b>	: 3/11/2022	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
Date & Time					Total Amount	3,819.02	4,086.34
Excess					Total (Inclusive of GST)		4,086.34
Status							
Signature							

Printed on 3/11/2022 3:24:07 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	03/11/2022 15:34 (SGT)
Reported by	Driver
Date of Accident	03/11/2022 07:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	WHITLEY ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGE8254Y
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LEONG YEW KAY
NRIC No	SXXXX224C
Email Address	LEONGUK18@GMAIL.COM
Mobile Phone No	(Phone) +65-97479718
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Hr-v
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

#### INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number	-

#### DRIVER

Name of Driver	HILLARY LEONG EN HUI
NRIC No	TXXXX769Z
Date Of Birth	03/05/2003
Occupation	Indoor

Vehicle Registration Number	XD3883T
Vehicle Manufacturer	
Vehicle Model	
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Commercial vehicle
Name of Driver	
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

### Describe Circumstances of the Accident

VB to police report T/20221103/2018

### Declaration

**We declare the foregoing particulars are true in every respect.**

Policyholder's Signature / Date &amp; Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel



**SINGAPORE  
POLICE FORCE**



T/20221103/2018

Police Station Of Origin:  
Bukit Merah West N.P.C  
500 Bukit Merah View #01-01 SINGAPORE  
159682  
Tel No: 1800-3779999

2 of 3

Report No. T/20221103/2018

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	HILLARY LEONG EN HUI	ID No.	T0311769Z
Related Vehicle	NIL	Contact No.	90463381
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 03/11/2022 at around 0715hrs, I was travelling on the lane second lane along Whitley Road towards Stevens Road. As I was approaching a bus stop, I slowed down to a stop before a yellow box to allow a bus to exit the bus stop. A heavy vehicle XD3883T belonging to Sika Singapore then hit the rear right of my vehicle.

I intended to exit my vehicle to assess the damage and to speak to the driver of the heavy vehicle. However, as the traffic was heavy, I did not manage to do so. The driver of the heavy vehicle did not exit his vehicle as well and gestured for me to move my vehicle. As the traffic was heavy at that time, I decided to move my vehicle and intended to stop it ahead at the roadside to speak to the other driver. I did not manage to filter left immediately due to the traffic and proceeded straight onto Stevens Road. When I looked at my rearview mirror, I realized that the heavy vehicle had made a turn onto Dunearn Road.

Hence, I was not able to exchange any particulars or speak to the driver of the heavy vehicle. The entire incident was captured by the dash cam of my vehicle. As such, I wish to lodge a report for record purposes and follow up by my insurance company.