

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP Lon Pac

Xiao Tong

WVW 222 7N ZH V 23 9417

ESTIMATE OF REPAIR

Veh# : SMK4472H

Model: VOLKSWAGEN SHARAN

Accident Date 7/11/2022

31/5/2017

Location ANG MO KIO STREET 21

3P: GBE7968L (LONPAC)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Del</i>	2,600.90	✓ 1350	
2	1 pc	Front bumper o/s retainer <i>new</i>	210.00	x	
3	10 pcs	Front bumper clips <i>new</i>		80.00	30
4	1 pc	Front o/s head lamp <i>new</i>	2,880.75	x	
5	1 pc	Front o/s fender <i>Del</i>	1,333.20	997	
6	1 pc	Front o/s fender inner garnish <i>new</i>	284.60	x	
7	6pcs	Front n/s fender screw <i>new</i>		48	x
8	2pcs	Front o/s & fender wheel guard <i>3M</i>	467.40	x	
9	8pcs	Front o/s fender wheel guard clips <i>3M</i>		128.00	x
10	1pc	Front o/s door <i>Del</i>	2880.75	2022	
11	1pc	Front o/s door striker <i>3M</i>	270.6	x	
12	2pcs	Front o/s door hinges <i>3M</i>	399.2	x	
13	1pc	Front o/s inner main frame weather strip <i>new</i>	333.90	x	
14	1 pc	Front n/s door window seal (outer) <i>new</i>	302.20	✓	
15	1 pc	Front o/s door window regulator <i>Del</i>	900.90	458	
16	1 pc	Front o/s door window motor <i>new</i>	955.75	x	
17	1pc	Front o/s door speaker <i>new</i>		800.00	x
18	1pc	Front o/s door inner board <i>Del</i>	1,479.60	999	
19	8pcs	Front n/s door inner board clips <i>new</i>		80.00	30
20	1pc	Front n/s door central locking unit <i>new</i>	850.00	x	
21	1 pc	Front o/s door wing mirror (whole set) <i>Del</i>	1,517.20	1095	
22	1 pc	Front o/s wheel rim <i>lit</i>	2,122.60	1280 (50)	
23	2pcs	Tyre <i>new</i>		400.00	x
24	1 pc	Front o/s suspension <i>new</i>	688.60	x	

25	1 pc	Front o/s knuckle	1,008.70	x	
26	1 pc	Front o/s wheel bearing	800.70	x	
27	1 pc	Front o/s ABS sensor	333.70	x	
28	1 pc	Front anti roll bar	540.70	x	
29	1 pc	Front o/s linkage	188.90	x	
30	1 pc	Front o/s lower arm	810.40	x	
			Sub Total:	24,161.25	1,536.00 0.00
				10%	0% 0%
			After Less %:	21745.13	1536.00 0.00
Labour					
1		To dismantle, straighten and welding	1,600.00	600	
2		To spray painting	1,000.00	800	
3		To remove and replace front under carriage	400.00	x	
4		To check wheel alignment (before & after)	260.00	80	
5		To reset check for fault code and resetting	280.00	120	
6		To check wiring	100.00	30	
7		To re seal anti rust	100.00	50	
			Sub Total:	3,740.00	
			Total:	27,021.13	
			After Less 20%:	21,616.90	

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Adrian Lj
L/s 08/11/22
06849



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 2520.88
L/s: 7.6K
761c