

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

04/11/22
Friday

25/10/2022

Owner: GRAVITY CAR LEASING PTE LTD

Not authorized
C1 Reg \$2100h
Returning After Pain
3 days

ESTIMATE TO REPAIR HONDA VEZEL - SMZ3778D

1pc	rear tailgate	953.30
1pc	rear tailgate "VEZEL" emble	
1pc	rear tailgate "HONDA" logo	
1set	rear tailgate windscreen moulding	
1pc	rear tailgate inner lock	
1pc	rear tailgate inner rubber	
1pc	rear tailgate inner garnish	
1pc	rear bumper	762.70
1pc	rear end panel	
1pc	rear end panel inner garnish	
1pc	rear end panel outer sensor	

Bu	\$ 1,210.90	✓
Ma	\$ 55.10	✓
Ma	\$ 58.50	✓
Ma	\$ 181.00	✓
Ma	\$ 198.40	X
Ma	\$ 135.20	X
Ma	\$ 420.50	X
Bu	\$ 986.30	✓
Ma	\$ 580.90	X
Ma	\$ 250.20	X
Ma	\$ 195.25	X

less 20%

\$ 4,272.25

\$ 854.45

\$ 3,417.80

1set rear reverse sensor

Shur s.nett \$ 280.00 200sh

remove & refix rear windscreen glass
wiring
tuffkote
sealant
spray painting
labour charges
Total

	\$ 120.00	✓
	\$ 60.00	15h
	\$ 60.00	3cl
Ma	\$ 80.00	401m
	\$ 800.00	22cl
	\$ 800.00	40cl
	\$ 5,617.80	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company