

ASS. REC. BY:

REF: C12/22011171kp

6

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S14C 5089B Yr Regn: 10, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1798

Colour: M.P. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 268172 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FUH03092246

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SIRIm / STD / RIm or

Tyre Size: F: Wanli 195/65R15

Rear Navigator

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 3/11/22

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 4/11/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S body & Frt N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/11 @ 7277.00 Cab

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ + RS. \$

Fuel

Others

TOTAL

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

NOT NOTHAW
MURRAY BY PAINT

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5089B

7277.00

AAD2211-

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

04 NOV 2022

SHC5089B

JTDKB3FUX03092246

TOYOTA

PRIUS GEN 4

03/11/2022

XB8480A/ China.

16/10/2020

PART	LIST
1 MIRROR ASSY, OUTER REAR VIEW, RH	\$ BR 1,436.60 ✓
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ All work 1,300.70 ✓
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$ Sm 193.50 X
1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$ rd 390.60 ✓
1 MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$ Sm 926.00 X
1 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$ Sm 321.10 X
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$ R 110.60 X
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$ R 97.50 X
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$ R 238.30 X
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ Mr 43.50 ✓
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ Mr 13.30 ✓
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ Mr 26.30 ✓
1 PANEL SUB-ASSY, REAR DOOR, RH	\$ Br 1,294.90 ✓
1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$ Sm 193.50 X
1 HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$ Sm 97.40 X
1 WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$ Sm 293.00 X
1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$ Sm 926.00 X
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$ Sm 206.70 X
1 TAPE, BLACK OUT, NO.2 REAR RH	\$ Mr 34.90 ✓
1 TAPE, BLACK OUT, NO.3 REAR RH	\$ Mr 15.40 ✓
1 TAPE, BLACK OUT, NO.1 REAR RH	\$ Mr 21.90 ✓
1 HINGE ASSY, REAR DOOR, LOWER RH	\$ R 87.10 X
1 HINGE ASSY, REAR DOOR, UPPER RH	\$ R 98.90 X
1 FENDER SUB-ASSY, FRONT RH	\$ Br 977.80 ✓
1 EMBLEM, SIDE PANEL, RH	\$ Mr 54.60 ✓
1 LINER, FRONT FENDER, LH	\$ CRT 210.30 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2211-

SHC5089B

1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>R</i>	871.50	X
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>Sm</i>	139.80	X
1	COVER, FRONT BUMPER	\$	<i>Bu</i>	521.00	✓
1	MOULDING, FRONT BUMPER SIDE, LH	\$	<i>W</i>	95.60	✓
1	RIM	\$	<i>Sm</i>	1,900.10	X
1	HUB CAP	\$	<i>Sm</i>	211.50	X
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	<i>Sm</i>	594.80	X
TOTAL		\$		13,944.70	
25%		\$		3,486.18	
		\$		10,458.53	

Special Nett

1	FRT FENDER LINER CLIP	\$	<i>na</i>	65.00	✓
1	RR FENDER LINER CLIP	\$	<i>na</i>	65.00	X
1	FRT BUMPER CLIP	\$	<i>na</i>	65.00	<i>60na</i>
1	TYRE	\$	<i>120SN Bu</i>	<i>200</i> 350.00	<i>60na</i>
1	FRT BUMPER RETAINER CLIP	\$	<i>na</i>	75.00	X
1	DOOR STICKER TRANSCAB	\$	<i>na</i>	100.00	<i>60na</i>
1	DOOR STICKER TEL. NO	\$	<i>na</i>	100.00	<i>60na</i>
1	DOOR TRIM CLIP	\$	<i>na</i>	75.00	X
1	DOOR WEATHERSTRIP CLIP	\$	<i>na</i>	80.00	X
TOTAL		\$		975.00	
TOTAL PARTS		\$		11,433.53	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>901</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>6001</i>

Trans-cab Auto Services Pte Ltd

AAD2211-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5089B

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>na</i>	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	<i>1100/</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i>	170.00	X
To transfer of tire, rim and on wheel balancing.	\$		170.00	<i>20/</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>20/</i>
To check steering geometry and computer wheel alignment	\$		220.00	<i>60/</i>
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X

TOTAL \$ 5,100.00

Over All Total \$ 16,533.53

(PART-BY-PART) Repair Days Days

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5089B

AAD2211-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY

SHC5089B

JTDKB3FUX03092246

TOYOTA

PRIUS **GEN 4**

03/11/2022

XB8480A/CHINA

16/10/2020

PART

1 GRILLE, RADIATOR, LOWER NO.1

LIST

	\$	<i>178.60</i>	178.60 ✓
TOTAL	\$		178.60
25%	\$		44.65
	\$		133.95