

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

UPTON AIRCONS & ENGINEERIN PTE LTD
3018 BEDOK NORTH ST 5 #04-27 EASTLINK
SINGAPORE 486132

Contact : 69132179 98556811

TAX INVOICE

Repair Code : CLM17451

Date in : 07/11/2022

Vehicle Num. : GBK7001U

Model : TOYOTA HIACE VAN TURBO 5DR MT

Chassis/Eng# : JTFHT02P209990561/1KDB049553

TP Budget Direct
17th Reg

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distal d.</i>	1	673.10	✓ 673.10
REAR BUMPER LOWER BRACKET <i>new</i>	4	48.00	✗ 192.00
REAR BUMPER SIDE RETAINER L/R <i>RH cancelled</i>	2	47.00	42. 94.00
REAR END PANEL (INNER) <i>2 Repir</i>	1	820.70	+ 820.70
REAR END PANEL (OUTER)	1	743.00	+ 743.00
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	48.00	+ 96.00
REAR EXHAUST SILENCER <i>Best</i>	1	1259.00	722 1,259.00
REAR RH FENDER <i>Buckled</i>	1	1546.90	1386 1,546.90
REAR RH FENDER AIR VENT <i>Distal d</i>	1	97.00	✓ 97.00
REAR RH FENDER INNER PANEL <i>Repir</i>	1	977.00	+ 977.00
REAR RH FENDER INNER TRIM BOARD <i>new</i>	1	489.50	+ 489.50
REAR RH FENDER INNER VERTICAL BRACKET <i>new</i>	2	79.00	+ 158.00
REAR RH TAILALMP LOWER GARNISH <i>Cancelled</i>	1	157.00	✓ 157.00
REAR RH TAILALMP LOWER GARNISH RETAINER <i>Cancelled</i>	1	53.00	✓ 53.00
REAR RH TAILLAMP <i>Cancelled</i>	1	265.00	✓ 265.00
REAR RH TAILLAMP INNER PANEL <i>Distal d</i>	1	570.30	✓ 570.30
REAR TAILGATE <i>Distal d</i>	1	1890.54	1714 1,890.54
REAR TAILGATE HINGES L/R <i>new</i>	2	67.00	✗ 134.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

UPTON AIRCONS & ENGINEERIN PTE LTD
3018 BEDOK NORTH ST 5 #04-27 EASTLINK
SINGAPORE 486132

Contact : 69132179 98556811

TAX INVOICE

Repair Code : CLM17451

Date in : 07/11/2022

Vehicle Num. : GBK7001U

Model : TOYOTA HIACE VAN TURBO 5DR MT

Chassis/Eng# : JTFHT02P209990561/1KDB049553

REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	<i>Rec</i>	2	17.00	<i>+</i>	34.00
REAR TAILGATE MECHANISM LOCK	<i>Rec</i>	1	264.00	<i>x</i>	264.00
REAR TAILGATE WEATHER STRIP	<i>ut</i>	1	391.00	<i>✓</i>	391.00
Subtotal before discount					10,905.04
Percentage discount 25%					2,726.26
Sub-total 1					8,178.78
REAR BUMPER CLIPS - SET	<i>Rec</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER REVERSE SENSOR	<i>Rec</i>	1	280.00	<i>x</i>	280.00
REAR RH FENDER 3D STICKER	<i>Rec</i>	1	1800.00	<i>700</i>	1800.00
REAR RH TAILLAMP CLIPS - SET	<i>Rec</i>	1	25.00	<i>10</i>	25.00
REAR TAILGATE '70KM' STICKER	<i>Rec</i>	1	25.00	<i>10</i>	25.00
REAR TAILGATE 3D STICKER	<i>Rec</i>	1	1200.00	<i>500</i>	1200.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>Rec</i>	1	50.00	<i>+</i>	50.00
REAR TAILGATE WINDSCREEN SEAL	<i>Rec</i>	1	80.00	<i>40</i>	80.00
REAR TAILGATE WINDSCREEN SEALANT	<i>Rec</i>	1	80.00	<i>40</i>	80.00
Subtotal before discount					3,590.00
Percentage discount 0%					0.00
Sub-total 2					3,590.00
Parts-total					11,768.78

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

UPTON AIRCONS & ENGINEERIN PTE LTD
 3018 BEDOK NORTH ST 5 #04-27 EASTLINK
 SINGAPORE 486132

TAX INVOICE

Repair Code : CLM17451

Date in : 07/11/2022

Vehicle Num. : GBK7001U

Model : TOYOTA HIACE VAN TURBO 5DR MT

Chassis/Eng# : JTFHT02P209990561/1KDB049553

Contact : 69132179 98556811

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

✓ 80.00

120 150.00

60 100.00

80 1,000.00

120 1,600.00

80 100.00

✓ 80.00

2420

Labour Total

3,110.00

Parts & Labour Total

14,878.78

*** This is a computer-generated document which requires no signature.***

page 3

Adrian C
 1/s 08/11/22

09 Days.

total: 8276.55

1/s: 6.6k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: