



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd	
		Document No.	3 Media Close	
		0	#01-03/06	
		Document Date	Singapore 138498	
		07/11/2022	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	05/09/2017	SLS0564Y	0	18437	66TP/SLS0564Y/071122

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU303569440	2ZRS082868	60	Shashitharan	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:GBD6373P ACC DATE:05/11/22 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00
2	B	BP-LAB2 CHECK WIRING AND REFOCUS HEADLAMP				198.00
3	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL				2376.00
4	B	BP-RES2 RESRPAY ACC AFF AREA				2624.00
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
6	B	BP-MECH2 CONDUCT WHEEL ALIGNMNET				198.00
7	1	U53395-47040 SEAL, HOOD TO FR END	1.00	55.80		55.80
8	2	U52115-47050 SUPPORT, FR BUMPER	1.00	86.20		86.20
9	3	U52119-47962 COVER, FR BUMPER	1.00	560.30		560.30
10	4	U53801-47080 FENDER SUB-ASSY, FR	1.00	1060.70		1060.70
11	5	U53875-47070 LINER, FR FENDER, RH	1.00	223.50		223.50
12	6	U75403-48010 EMBLEM SUB-ASSY,	1.00	77.40		77.40
13	7	U81145-47691 UNIT, HEADLAMP	1.00	2852.40		2852.40

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	10,610.30
	Please acknowledge receipt of vehicle	Parts 4,916.30 Labour 5,694.00 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00% 742.72 Less 0.00	Amount Due 11,353.02

Customer Copy