

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 09 Nov 2022

Preliminary Advice

Vehicle No	: SMT7737C	Accident Date	: 03/11/2022
Make	: HONDA ODYSSEY	Policy No.	: MPC22P00110300
Assignment Date	: 08/11/2022	Excess	: S\$0.00
Date of Inspection	: 08/11/2022	Est. Duration of Repair	: 5
Inspection At	: VIN'S MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE, #03-03, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,231.00
Revised Amount	:S\$	4,475.00
Check Items (Estimated)	:S\$	121.00
Total	:S\$	4,596.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 85,000.00
COE / PARF Rebate	:S\$ 40,103.00
Salvage Value	:S\$

Margin for Repair

:S\$ 44,897.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.