

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : **ECICS LIMITED**
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/112022/5754
Date : 05-11-2022
Accident Date : 03-11-2022

Vehicle Details

Make & Model : Honda ODYSSEY 2.4 EXV-S CVT
SR
Chassis No : JHMRC1890GC204187
Registration No : SMT7737C

S/N	Description	Qty	Amount (\$\$)
1	TAILGATE <i>u</i>	1.00	\$820.00
2	TAILGATE GLASS RH MOULDING <i>na</i>	1.00	\$30.00
3	TAILGATE GLASS LH MOULDING <i>na</i>	1.00	\$30.00
4	TAILGATE GLASS TOP MOULDING <i>na</i>	2.00	\$60.00
5	TAILGATE GLASS SIDE MOULDING <i>na</i>	2.00	\$80.00
6	TAILGATE EMBLEM <i>na</i>	1.00	\$40.00
7	TAILGATE CENTRE REFLECTOR <i>cut</i>	1.00	\$160.00
8	TAILGATE RH REFLECTOR <i>ca</i>	1.00	\$280.00
9	TAILGATE LH REFLECTOR <i>ca</i>	1.00	\$280.00
10	TAILGATE LOWER CHROME MOULDING <i>?com/invoice</i>	1.00	\$110.00 <i>150</i>
11	TAILGATE INNER TRIMBOARD <i>2AA</i>	1.00	\$180.00
12	TAILGATE REVERSE CAMERA <i>Xna</i>	1.00	\$420.00 <i>X</i>
13	TAILGATE INNER LOCK <i>cut</i>	1.00	\$110.00
14	TAILGATE RUBBER <i>na</i>	1.00	\$80.00
15	REAR BUMPER <i>de</i>	1.00	\$480.00
16	REAR BUMPER PARKING SENSOR <i>cut</i>	2.00	\$440.00 <i>s/n-200</i>
17	REAR BUMPER RH SIDE RETAINER <i>Xna</i>	1.00	\$20.00 <i>X</i>
18	REAR BUMPER LH SIDE RETAINER <i>Xna</i>	1.00	\$20.00 <i>X</i>
19	REAR BUMPER CLIPS <i>na</i>	10.00	\$20.00
20	REAR END PANEL <i>repair</i>	1.00	\$350.00 <i>XR</i>

Margin: 10%

\$4,010.00
\$401.00

21	WINDSCREEN GUM <i>na</i>	1.00	\$80.00 <i>80</i>
22	TO REMOVE AND REFIX TAILGATE GLASS <i>na</i>	1.00	\$180.00 <i>120</i>
23	TO REPAIR DAMAGES	1.00	\$680.00 <i>500</i>
24	TO SPRAY PAINTING (PEARL)	1.00	\$880.00 <i>700</i>

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Subtotal w/o GST:

\$6,231.00

3080

200

1360

4640

Resue

Hp 90010068

5 days

~~48~~ P/P

08/11/22 @ 1345

EXCESS: TBA

REMARK

Resue after repair
before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Iswan

This is a computer-generated document. No signature is required.