



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE
417883
ON BEHALF OF EDSSEL GOH WEE KIAT

Ref: CS/TP22011139/Uwy3m4
Date: 07/12/2022
Code: TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SNF 3974Y
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	08/11/2022

2. Vehicle Particulars & Condition

Make & Model	BMW 535I (A)	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBAFR72030C580586	Colour	WHITE
Odometer	166512 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35 ZR19	MICHELIN	6 mm
L/H Front Tyre	255/35 ZR19	MICHELIN	6 mm
R/H Rear Tyre	275/35 ZR19	MICHELIN	6 mm
L/H Rear Tyre	275/35 ZR19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/11/2022	Inspection Date	08/11/2022
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**