

ASS. REC. BY: Tajp

REF:

04/19/2011/41/TP93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

94210

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF 277ATYr Regn: 296, Aug

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Canter FEAO1 c.c. 2998Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 418537

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEAO1BA 20334

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

195/85R15

R: _____

(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal. 8 mmR/Bal. 8/8 mmL/Bal. 8 mmL/Bal. 8/8 mm

D.O.A. _____

D.O.I. 9/11/22

Survey held at

MS Car Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Repair Format: _____

Lump Sum / L&L: _____

SJE :

Date of Survey :

Contacts :

Vehicle Nos : GBF 2779T

Model :

Year :

MAKE & MODEL : MITSUBISHI CANTER FUSO

ITEM	DESCRIPTION	Qty	
1	Tail gate 2000 1-X RH-ang	2	\$5,689.50
2	Tail gate hinge R	4	\$684.80
3	Tail gate lever L+R n X	2	\$245.40
4	Tail gate sticker - MITSUBISHI n	1	\$276.90
5	Rear floor panel n X	1	\$4,932.90
6	Tail lamp L+R C	2	\$564.80
7	Tail lamp bracket L+R n X	2	\$187.60
8	Rear number plate lamp C	1	\$89.40
9	Rear number plate bracket n X	1	\$95.20
11	Rear chassis member L+R R	2	REPAIR
12	Rear spare tyre bracket n X	1	\$458.90
13	Rear exhaust pipe 695 b	1	\$951.50
14	Rear exhaust pipe mounting n X	2	\$68.80
15	Rear exhaust pipe bracket n X	1	\$49.30
16	Rear exhaust pipe gasket n	1	\$35.80
	3661.90 Parts Sub Total		\$14,330.80
	3295.71 Discount 10%		\$1,433.08
	Parts Total		\$12,897.72
	Special Nett		
1	Tail gate sticker - 70 km/h n	1	\$15.00
2	Rear number plate 30 b	1	\$50.00
3	Rear reinforcement beam 600 b	1	\$750.00
4	Rear boot sickerr RL 600 n	2	\$1,800.00
5	Tail gate alluminium plate rivet 50 n	10	\$100.00
	1295		
	Special Nett Total:		\$2,715.00
	Labour		
1	To R & R accident damage parts, to cut/weld, knock and realign accident affected area 700	1	\$1,200.00
2	To putty and respray accident affected area. 600	1	\$1,000.00
3	To rust proof accident affected area 30	1	\$120.00
4	To R & R rear cabin assy n X	1	\$1,500.00

