

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SVV 82776 Yr Regn: 10/11/10Type: 1. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes-Benz GIA 180 c.c. 1595Colour: Blue A/C: Insured / Std / Nil / NASp. Reading: 13431 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/Nr: WDC15694775686319Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SDM / STD A/Rim orTyre Size: F: 135/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMIT

TOYO / YOKO or: ContinentalFront: 4 mmR/Bal. 4 mmU/Bal. 4 mmD.O.A. 5/11/92 cycleSurvey held at: Front RHDes. of Damages: Fit / Rear / O/S / N/S / UIC / Rooktop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction

MV. 133K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.J. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation

\$ + RS. \$ _____

Phone

Others

TOTAL



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SJV8277G

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

60757
SJV8277G / 20/01/2020
/ 23431
WDC1569422J6863190
27091031944568
MB/GLA 180 SPORT UTILITY VEH
026 667 Demin Blue / 043 381 ARTICO/FabB

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WL001605	Credit	08/11/2022/ 14:17	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 2070005946-02 // 5-11-2022								
DRIVE IN/TP VEH NUMBER : 5-11-2022 // GBE6128B - LONPAC								
DATE IN/DATE SURVEY:								
DIRECT SETTLEMENT BY:								
A BPILAB								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								1920 ✓ 2400.00
A BPIRES								
RESPRAY FRONT BUMPER & RH/FRONT FENDER								1600 ✓ 1800.00
A BPILAB							0.10	380.00 ✓
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								120.00 ✓
A BPILAB								
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT								540.00 ✓
A BPILAB								
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT								60.00 ✓
S BPNSUB								
LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT)								
WHEEL BALANCE AND INSTALL NEW VALVE HEAD								240.00 ✓
A 54099101								
EXTRA WORK TO PROGRAM AND CODE HEADLAMP CONTROL UNIT(AFTER QUICK TEST)								180.00 ✓
A 97250001								
CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM					1.00	1430.59	00.00	1430.59 ✓
M FRONT BUMPER / DD					1.00	67.92	00.00	67.92 ✓
M FRONT BUMPER MB EMBLEM / MC					1.00	66.06	00.00	66.06
M RH/SIDE INNER COVER BRACKET / X nn					1.00	72.63	00.00	72.63 ✓
M RH/SIDE COVER BUMPER AREA / BR					1.00	195.43	00.00	195.43
M OUTER DISTANCE SENSOR / X nn					1.00	7.10	00.00	42.60 ✓
M SPACER RING / MC					6.00	984.80	00.00	984.80 ✓
M CTR/SILVER COVER BUMPER AREA / CUT					1.00	164.77	00.00	164.77 ✓
M RH/SIDE BOTTOM BLACK TRIM BUMPER / BR					1.00			

Confirmed & accepted by

Go Chee Han

DID: 6771 4336 HP - 9181 7717

Email: chee.han@cycleandcarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Support & Service Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJV8277G

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

60757

SJV8277G / 20/01/2020

/ 23431

WDC1569422J6863190

27091031944568

MB/GLA 180 SPORT UTILITY VEH

026 667 Demin Blue / 043 381 ARTICO/FabB

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	08/11/2022/ 14:17	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M TOP BASIC MOUNTING FOR BUMPER	1	X nn			1.00	211.54	00.00	211.54
M RH/FRONT FENDER	1	OP			1.00	910.28	00.00	910.28
M RH/COVER FENDER & BUMPER AREA	1	7	CUT		1.00	225.49	00.00	225.49
M RH/FRONT FENDER BRACKET	1	X nn			1.00	13.54	00.00	13.54
M RH/WHEEL ARCH COVER	1	CUT			1.00	191.69	00.00	191.69
M EXPANSION RIVET	6	nk			6.00	6.09	00.00	36.54
M CROSS MEMBER	1	X nn			1.00	350.27	00.00	350.27
M RH/FRONT BUMPER SUPPORT	1	X nn			1.00	17.09	00.00	17.09
M RIGHT HEADLAMP UNIT	1	GR			1.00	2653.89	00.00	2653.89
M LIGHT RANGE CONTROL UNIT	1	X nn			1.00	788.90	00.00	788.90
M RH/FRONT DISK WHEEL	1	CUT			1.00	720.24	00.00	720.24

Steve (LKK)

9/11/22, 10.20

m

P/P

17 B/Ly

5 & 4y

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarrage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service - Pandan Loop

Confirmed & accepted by LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp is allowed

Nett 14,864.27
7% GST on 14864.27 1040.50
Total Payable 15,904.77

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg