

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internation			nale Des Experts En Automobile		<u> </u>	CS3/LPC22007491	
	LONPAC INSURAN	NCE BHD			Ref:	-009/LP02	2007491/y3	
	300 BEACH ROAD #17-04/07 THE CO		APORE 199555		Date:	-05/00/202	● 07/11/2022	
					Code:	LPC2		
•	Policy Particulars :- (THIRD PARTY CLAIM)							
	Insured Veh.	XB 9997U		Veh. Inspected	d	YP 2170Z		
	Policy No.			Coverage (\$)		0.00		
	Claim No.			Excess (\$)		0.00		
	Assign From	GERALD POH	ENG HUEY NI	Assign Date		05/06/202	2 07/11/2022	
2.			Vehicle Partic	ulars & Condit	ion			
	Make & Model			c.c		0		
	Engine No.	HIDDEN		Year of Reg.				
	Chassis No.			Colour				
	Odometer	-		Steering				
	Brakes			Modification				
	General							
<b>3</b> -			Condition	ons of Tyres				
		Size		Make		Balance		
	R/H Front Tyre					mm		
	L/H Front Tyre					mm		
	R/H Rear Tyre					mm		
	L/H Rear Tyre					mm		
١.			Description	n of Damages				
5.	General Information							
	Accident Date	02/08/2022		Inspection Da	te	08/08/2022	2	
	Survey held at	EXCEL MOTOR	3					
		BLK 5032 ANG #01-297 SINGAPORE 5	MO KIO INDUST 69535	RIAL PARK 2				
5a.	Remarks							
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.							