

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0976/2022/EQ
DATE : 8-Nov-22
WIP : 49415

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/11/2022
YOUR INSURED VEH NO : SNB 3785 Y

Allianz Insurance Singapore Pte Ltd

79 Robinson Road

#09-01

Singapore 068897

Attn: Motor Claims Dept

OWNER'S NAME : MR TEO HUI YU RICHARD
ADDRESS : BLK 10 WHAMPOA EAST
#23-29, EIGHT RIVER SUITES
SINGAPORE 338521
TELEPHONE : HP +65 90901690
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : PNPV2017-00004773-05
VEHICLE NO : SFW 8998 B
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 28/6/2014
ENGINE NO : CXS 095942
CHASSIS NO : WAUZZZ8V2E1037387
MILEAGE : 90,600
DATE IN : 7-Nov-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Nov-22
PLACE OF ACCIDENT : 19 RECREATION ROAD, SINGAPORE 546516

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFW 8998 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 ✓	
3	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00 ✓	
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	700 x 3 \$ 2,800.00	2100
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER, LHS SILL PANEL AND LHS UPPER A-PILLAR.	250 x 3 \$ 4,700.00	2350
TOTAL LABOUR CHARGES		: \$ 8,560.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFW 8998 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY.	S/N \$	2,400.00	? ✓
7	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	✓
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	✓
9	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	✓
TOTAL LABOUR CHARGES		:	\$ 12,144.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFW 8998 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>OR</i>	1	\$ 2,377.00	✓
2	FRONT BUMPER FIXING PARTS <i>X nn</i>	1	\$ 195.00	
3	FRONT BUMPER STRIP MOLDING - LH <i>? X nn</i>	1	\$ 182.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X nn</i>	1	\$ 175.00	
5	FRONT BUMPER PULL STRAP - LOWER <i>X nn</i>	4	\$ 231.00	
6	FRONT BUMPER GUIDE SECTION - LH <i>BT</i>	1	\$ 43.00	42.80 ✓
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>m/s</i>	1	\$ 122.00	121.50 ✓
8	RADIATOR GRILLE <i>X nn</i>	1	\$ 765.00	
9	RADIATOR GRILLE COVER <i>X nn</i>	1	\$ 109.00	
10	FRONT BUMPER FOAM FILLER PIECE <i>X nn</i>	1	\$ 154.00	
11	FRONT BUMPER REINFORCEMENT BEAM COVER <i>X nn</i>	1	\$ 63.00	
12	FRONT BUMPER REINFORCEMENT BEAM <i>X nn</i>	1	\$ 847.00	
13	CAUTION SIGN STICKER <i>X nn</i>	1	\$ 16.00	
14	AIR CONDITIONER STICKER <i>X nn</i>	1	\$ 9.00	
15	HORN LOW TONE - LH <i>? X nn</i>	1	\$ 213.00	
16	FRONT FENDER - LH <i>DD</i>	1	\$ 954.00	✓
17	FRONT FENDER ATTACHMENT PARTS <i>X nn</i>	1	\$ 75.00	
18	FRONT FENDER BRACKET <i>? X nn</i>	1	\$ 46.00	
19	FRONT FENDER RIVET <i>hc</i>	6	\$ 23.00	22.80 ✓
20	FRONT FENDER BRACE <i>? BT</i>	1	\$ 107.00	✓
SUB TOTAL SPARE PARTS		:	\$ 6,706.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFW 8998 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER BRACKET - LH ? X nn	1	\$ 31.00		
22	FRONT FENDER CLOSING ELEMENT - LH ? X nn	1	\$ 37.00		
23	FRONT FENDER INSULATION - LH ? X nn	1	\$ 48.00		
24	FRONT WHEEL HOUSING LINER - LH - BR	1	\$ 183.00	✓	
25	HEADLIGHT - LH - BR	1	\$ 2,810.00	✓	
26	HEADLIGHT POWER MODULE ? X nn	1	\$ 635.00		
27	HEADLIGHT GAS DISCHARGE ? X nn	1	\$ 454.00		
28	HEADLIGHT GAS DISCHARGE CONTROL UNIT ? X nn	1	\$ 1,279.00		
29	HEADLIGHT HOSE - LH X nn	1	\$ 60.00		
30	LIFT CYLINDER - LH X nn	1	\$ 211.00		
31	LIFT CYLINDER HOSE X nn	1	\$ 204.00		
32	LIFT CYLINDER PUMP X nn	1	\$ 172.00		
33	LIFT CYLINDER WASH WATER RESERVOIR ? DEF	1	\$ 226.00	225.50 ✓	
34	LIFT CYLINDER WINDSCREEN WASHER SYSTEM PUMP ? X nn	1	\$ 138.00		
35	OUTSIDE TEMPERATURE SENSOR BRACKET X nn	1	\$ 21.00		
36	RADIATOR AIR GUIDE - LH X nn	1	\$ 28.00		
37	RADIATOR AIR GUIDE - UPPER CENTRE X nn	1	\$ 14.00		
38	FRONT DOOR - LH nn R X nn	1	\$ 3,265.00		
39	FRONT DOOR ATTACHMENT PARTS X nn	1	\$ 252.00		
40	BONDING AGENT nn X nn	1	\$ 51.00		
SUB TOTAL SPARE PARTS			:	\$ 10,119.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFW 8998 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	CLEANING SOLUTION ✓ X nn	1	\$ 74.00	
42	FRONT DOOR CATCH - LH X nn	1	\$ 116.00	
43	FRONT EXTERIOR WING MIRROR MOUNTING - LH X nn	1	\$ 1,130.00	
44	FRONT WING MIRROR CAP - LH X R	1	\$ 180.00	
45	FRONT WING MIRROR GLASS - LH X nn	1	\$ 239.00	
46	FRONT WINDOW SLOT SEAL TRIM STRIP - LH X nn	1	\$ 346.00	
47	FRONT WINDOW GUIDE TRIM STRIP - LH X nn	1	\$ 287.00	
48	NOISE INSULATION X nn	1	\$ 377.00	
49	FRONT ALUMINIUM RIM - LH - M	1	\$ 1,303.00	✓
50	CONTROL ARM - LH LOWER 7 BT	1	\$ 394.00	393.50 ✓
51	FRONT WHEEL BEARING HOUSING 7 BT	1	\$ 628.00	✓
52	FRONT WHEELHUB BEARING 7 NEC	1	\$ 554.00	✓
53	CONTROL ARM GUIDE JOINT - LH BT	1	\$ 137.00	✓
54	COUPLING ROD 7 X nn	1	\$ 105.00	
55	GAS SHOCK ABSORBER 7 BT	1	\$ 282.00	✓
56	TRACK ROD 7 BT	1	\$ 99.00	98.20 ✓
57	TIE ROD END - LH 7 BT	1	\$ 126.00	125.50 ✓
58	FRONT NO PLATE X nn	S/N	\$ 60.00	
59	LHS FRONT TYRE 7 X nn	S/N	TBC	
60	SUNDRIES 7 NEC		\$ 800.00	171.70 ✓

TOTAL SPARE PARTS

: \$ 24,062.00

TOTAL LABOUR CHARGES

: \$ 12,144.00

GRAND TOTAL

: \$ 36,206.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



100, UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Steve (LKK)
: 9/11/22, 11.00h
: 00- L1 MC
: EXCESS - ?
: PIP, N, BL by 9/10 dys

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT