

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22011152/KWP3Q2
Date: 18/11/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNW00137442101	
Claimant Vehicle No : SMY6593E	Insured Vehicle No : GZ6689D	
Date of Loss: 27/10/2022	Nature of Claim: TP	Claim No: SNM22D207746/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY6593E		
Make & Model:	VOLKSWAGEN PASSAT B8, 1.8 TFSI AT 3G24JZ (A)	Engine No:	CJS310143
Reg. Date:	13/12/2019 (Man. Year: 2019)	Chassis No:	WVWZZZ3CZKE138115
Colour:	Metallic Dark Grey	Odometer:	69768 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,300.99	485.99	1,815.00	78.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	630.00	300.00	32.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,230.99	1,115.99	2,115.00	65.46
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	3,230.99	900.00	2,330.99	72.14

INSPECTION

Date of Assignment:	08/11/2022	
Date Inspected:	09/11/2022	Inspected At: Eng Heng Automobil Trading Co (HQ) Blk 10 #01-01 Ang Mo Kio Part 2A AutoPoint Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Nov 2022)

Parts: 143 VOLKSWAGEN PASSAT B8 1.8 TFSI AT 3G24JZ (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMY6593E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LEFT DOOR	Repair	1,550.00 F	*- F
2	1		*FRONT LEFT DOOR HANDLE -OUTER	Serviceable	265.00 F	*- F
3	1		*FRONT LEFT DOOR MIRROR ASSEMBLY	Dented / Cut	485.99 F	*485.99 F
Total Parts (S\$)						2,300.99 485.99

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT AND REPLACE DOOR ,HANDLE AND DOOR MIRROR	New	380.00	280.00
2	RESPRAY PAINT FRONT LEFT DOOR ,DOOR HANDLE AND DOOR MIRROR	New	550.00	350.00
Gross Labour Cost (S\$)			930.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >