## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd

> 64 Cecil Street #04-00 IOB Building Singapore 049711

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

> Paya Ubi Industrial Park Singapore 408933

Attn: Zuhaidah Bte Samsuri 09 Nov 2022 Date:

# **Preliminary Advice**

Vehicle No : SMT1891D Accident Date : 02/11/2022

Policy No. : D21MFL0005172 01 Make : KIA CERATO

Assignment Date : 08/11/2022 Excess : S\$0.00 Date of Inspection : 08/11/2022 Est. Duration of Repair : 6

: KAN FOOK SING MOTOR WORKSHOP (DEFU) Inspection At

BLK 8 DEFU SOUTH STREET 1, DEFU INDUSTRIAL CITY #04-29

SINGAPORE 533758

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,860.40
Revised Amount	:S\$	4,957.20
Check Items (Estimated)	:S\$	2,614.80
Total	:S\$	7,572.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	86,000.00
COE / PARF Rebate	:S\$	33,040.00
Salvage Value	:S\$	

Margin for Repair :S\$ 52,960.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	ylk
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.