

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 06 Jan 2023

Preliminary Advice

Vehicle No	: SKC3097E	Accident Date	: 04/11/2022
Make	: HYUNDAI ELANTRA	Policy No.	: SP2000465454-01
Assignment Date	: 08/11/2022	Excess	: S\$600.00
Date of Inspection	: DESKTOP SURVEY	Est. Duration of Repair	: 4
Inspection At	: SUCCESS UNITED PTE LTD (HQ) 2 KAKI BUKIT AVE 2 #01-33, KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,124.00	(Estimate \$5,047.00+Supplementary \$77.00)
Revised Amount	:S\$	3,129.60	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	3,129.60	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	16,486.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,514.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.