Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. From: LI

Ltd. 79 Robinson Road #09-01

79 (Vobilison (Voad #09-0)

Singapore 068897

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Sharon Lim Date: 10 Nov 2022

Preliminary Advice

Vehicle No : SKC3097E Accident Date : 04/11/2022

Make : HYUNDAI ELANTRA Policy No. :

SP2000465454-

: S\$600.00

01

• 4

Assignment : 08/11/2022 Excess

Date

Date of : DESKTOP SURVEY Est. Duration of

Inspection Repair

Inspection At : SUCCESS UNITED PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 5,047.00
Revised Amount :S\$ 2,357.10
Check Items (Estimated) :S\$ 2,101.40
Total :S\$ 4,458.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 42,000.00 COE / PARF Rebate :S\$ 16,486.00

Salvage Value :S\$

Margin for Repair :S\$ 25,514.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on part by part basis due to no 2nd hand parts available.
 - Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.