

SLS5939S.

TP MS16.

Mazda 3.

Veren.

JM6BN22A8J0176127.

Front Bumper	{ NP Ver	1083.30. +
Front Bumper Clips.		30(SN) +
Front Bumper Side Holder LH.	NP	38.30. +
Headlamp LH.	cut	3565 ✓
Front LH Fender	Dented	417.50. ✓
Front LH Fender Inner Shield	Dehnd	185.10. ✓
Front LH Fender Inner Shield Clips.	NP	30(SN) ✓
Front LH Wheel Rim.	NP	1000(SN) +
Front LH Wing Mirror	Damaged	456.60 ✓
Front LH Wing mirror Signal Lamp.	could	85.80. ✓
Front LH Door	Repair	1120.90 +
Front LH Door Glass	cut	386.90 ✓
Front LH Door Frame Black Tape.	repair	50(SN) +

SLS5939S.

Rees LH Door Regis

1219.40 f

Rees LH Door Frame Black Tape ^{17h} 50(SN) f

5086.50. S.N: 30

less 20%: 4069.52

Panel Beating

Spray Painting.

Wiring.

To transfer front and rear door fittings.

To apply tuff coat.

~~900~~ 500.

1270

~~1000~~ 700

~~50~~ 30

300 x

~~150~~ 40.

total: 5369.52

L/S 4.3K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4.3K