



# DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD  
29 UBI ROAD 4, DICKSON AUTO CENTRE  
SINGAPORE 408619  
TEL: 6668 1122 | FAX: 6668 1123

## QUOTATION

### QUOTATION FOR

NAME: Income Insurance Limited  
COMPANY NAME: Income Insurance Limited  
STREET ADDRESS: 75 Bras Basah Road, Income Centre  
POSTAL CODE: Singapore 189557  
PHONE: 6788 1777

DATE: 7 Nov 2022

REF: SLM6323T  
VEHICLE NO.: SLM6323T  
MAKE: TOYOTA  
MODEL: COROLLA  
PREPARED BY: MR POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
<b>LABOUR</b>							
1	TO REMOVE & REFIT ALL REAR LIGHTING & WIRING, TEST FOR PROPER FUNCTIONING	1		\$80.00	\$ 80.00		\$ 80.00
2	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS, CUT & WELD IF NECESSARY AND REALIGN	1		\$800.00	\$ 800.00		\$ 800.00
3	TO PROVIDE SKILL LABOUR & MATERIAL TO PAINT NEW PARTS & PANELS	1		\$800.00	\$ 800.00		\$ 800.00
<b>PARTS</b>							
1	REAR BUMPER	1		\$495.00	\$ 495.00	/	\$ 495.00
2	REAR BUMPER CLIPS	10		\$5.00	\$ 50.00	30	\$ 50.00
3	REAR BUMPER SIDE RETAINER LH & RH	2	1 LH, 1 RH	\$96.10	\$ 192.20	/	\$ 192.20
4	REAR BUMPER REFLECTOR LH & RH	2		\$57.60	\$ 115.20	50	\$ 115.20
5	TAIL LAMP LH & RH	2		\$338.00	\$ 676.00	//	\$ 676.00
6	RR BOOT	1		\$710.00	\$ 710.00	R	\$ 710.00
7	RR BOOT LOGO	1		\$68.00	\$ 68.00	X	\$ 68.00
8	RR BOOT COROLLA LOGO	1		\$39.20	\$ 39.20	/	\$ 39.20
9	RR LH FENDER	1		\$955.00	\$ 955.00	R	\$ 955.00
10	RR LH FENDER INNER SHIELD	1		\$98.50	\$ 98.50	X	\$ 98.50
11	RR LH FENDER INNER SHIELD CLIPS	4		\$5.00	\$ 20.00	X	\$ 20.00

SUBTOTAL	\$ 5,099.10	SUBTOTAL	\$ 5,099.10
GST 7%	\$ 356.94	GST 7%	\$ 356.94
TOTAL	\$ 5,456.04	TOTAL	\$ 5,456.04

### REMARKS:

Irfin 90097659

8/11/22

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

L/S S. S. S. S.

FOR DICKSON AUTO CARE CENTRE PTE LTD

TOTAL = 1386.3



25% = 346.

(AUTHORISED SIGNATURE)

(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

Final T: 2370

20% = 1896



**DICKSON GROUP**

Your Trusted Automotive Solutionist

**DICKSON AUTO CARE CENTRE PTE LTD**  
29 UBI ROAD 4, DICKSON AUTO CENTRE  
SINGAPORE 408619  
TEL: 6668 1122 | FAX: 6668 1123

SUPPLEMENTARY QUOTATION

QUOTATION FOR

**NAME:** Income Insurance Limited  
**COMPANY NAME:** Income Insurance Limited  
**STREET ADDRESS:** 75 Bras Basah Road, Income Centre  
**POSTAL CODE:** Singapore 189557  
**PHONE:** 6788 1777

**DATE:** 8 Nov 2022

**REF:** SLM6323T  
**VEHICLE NO.:** SLM6323T  
**MAKE:** TOYOTA  
**MODEL:** COROLLA  
**PREPARED BY:** MR POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>PARTS</u>						
1	REAR END PANEL	1		\$608.10	\$ 608.10	dent (R)	\$ 608.10
SUBTOTAL					\$ 608.10	SUBTOTAL	\$ 608.10
GST 7%					\$ 42.57	GST 7%	\$ 42.57
TOTAL					\$ 650.67	TOTAL	\$ 650.67

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

*[Handwritten signature]* 11/11/2022 92097659

(CUSTOMER'S SIGNATURE AND  
COMPANY STAMP)

FOR DICKSON AUTO CARE CENTRE PTE LTD

*[Handwritten signature]*



(AUTHORISED SIGNATURE)

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: