



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

bizSAFE
S T A R



Vehicle number	SLQ8767L
Make / Model	HONDA VEZEL
Chassis number	RU31230386
Accident date	6/11/22
Reference	2211-02

Qty	Particulars	Unit Price - SGD
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	609.40 Scr
1	REAR BUMPER RETAINER RH	44.20 ? cra
1	REAR CORNER BUMPER RH	198.72 Scr
1	REAR WHEEL ARC GARNISH RH	205.70 scr
1	REAR FENDER RH	720.72 scr
1	REAR FENDER INNER SHIELD RH	181.60 ? art
1	TAILLAMP RH NN	554.40 X
1	REAR ABSORBER RH	231.00 ? dent
1	REAR WHEEL HUB W BEARING RH	289.30 ? dent
		3035.04 1553-6
	Less 20%	607.01 310.7
	Subtotal	2428.03 1242.8
	Balance C/F	2428.03
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	REAR BUMPER CLIP	30.00 Nec
1 SET	WHEEL ARC GARNISH CLIP	30.00 Nec
1 SET	REAR FENDER INNER SHIELD CLIP	30.00 Nec
1	RIM RH LOCAL REPAIR	90 400.00 R (scr)
	Subtotal	490.00 180
	Balance C/F	2918.03
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTINGS SYSTEM	120.00 X
2	REMOVE & REFIT REVERSE SENSOR TO FACILITATE REPAIR	150.00 30
3	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	200.00 807
4	REMOVE & REPLACE REAR UNDERCARRIAGE	200.00 X 50
5	PANEL BEATING ON AFFECTED AREAS	800.00 X 400
6	SPRAY PAINTING ON AFFECTED AREAS	800.00 X 400
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 X
	Subtotal	2420.00 2382.8
	Grand total	5338.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10/11/22

FT

2380
20% = 476
= 1900