

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



**HD PERFECT
AUTOWORK PTE LTD**

xiao Chen,

DATE : 04.11.2022

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBF7005K**
MODEL : **NISSAN NV200**
DATE OF ACCIDENT : 03.11.2022
TIME OF ACCIDENT : 17:10 HRS

VM20102518

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR SIDE PANEL LH <i>Distorted</i>	1	\$ 1,555.00	\$ 1,555.00
2	REAR SIDE INNER PANEL LH <i>Bent</i>	2 1	\$ 1,464.00	\$ 2,928.00
3	REAR SIDE INNER AIR VENT LH <i>new</i>	1	\$ 72.00	\$ 72.00
4	REAR SIDE PANEL RAILWAY LH <i>behnd</i>	1	\$ 484.30	\$ 484.30
5	REAR SIDE PANEL RAILWAY END LH <i>new</i>	1	\$ 42.60	\$ 42.60
6	REAR WHEEL HOUSE PANEL LH (INNER) <i>Rips</i>	1	\$ 599.40	\$ 599.40
7	REAR WHEEL HOUSE PANEL LH (OUTER) <i>Rips</i>	1	\$ 403.00	\$ 403.00
8	REAR ABS SENSOR <i>LH Rnd</i>	2	\$ 395.40	\$ 790.80
9	REAR WHEEL RIM <i>cut &</i>	2	\$ 264.50	\$ 529.00
10	REAR AXLE <i>Best</i>	1	\$ 2,159.00	\$ 2,159.00
11	REAR SHOCK ABSORBER <i>LH Best</i>	2	\$ 97.70	\$ 195.40
12	REAR WHEEL HUP C/W BEARING <i>LH Rnd</i>	2	\$ 430.50	\$ 861.00
14	TAIL LAMP LH <i>Crashd.</i>	1	\$ 294.60	\$ 294.60
15	TAIL LAMP PANEL LH <i>Rips</i>	1	\$ 475.00	\$ 475.00
16	TAIL LAMP INNER PANEL LH <i>Rips</i>	1	\$ 176.00	\$ 176.00
17	REAR BUMPER <i>behnd</i>	1	\$ 566.90	\$ 566.90
18	REAR BUMPER SPONGE <i>new</i>	1	\$ 145.89	\$ 145.89
19	REAR BUMPER SIDE RETAINER 2 <i>LH Rnd</i>	2	\$ 39.70	\$ 79.40
20	REAR WHEEL HUP CAP <i>Missing</i>	2	\$ 89.60	\$ 179.20

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBF7005K**
 MODEL : **NISSAN NV200**
 DATE OF ACCIDENT : 03.11.2022
 TIME OF ACCIDENT : 17:10 HRS

7426.40
 6683.76

TOTAL PRICE \$ 12,536.49
 LESS 10% \$ 1,253.65
SUB TOTAL PRICE \$ 11,282.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
2	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>20</i>
3	REAR SIDE INNER PANEL SEALANT <i>3M</i>	1	\$ 300.00	\$ 300.00 <i>x</i>
4	REAR INNER SIDE PANEL SEALANT <i>new</i>	1	\$ 300.00	\$ 300.00 <i>x</i>
5	REAR SIDE PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 <i>60</i>
6	REAR SIDE PANEL GLASS SEALANT <i>new</i>	1	\$ 180.00	\$ 180.00 <i>70</i>
7	REAR SIDE PANEL GLASS INNER SHIELD <i>new</i>	1	\$ 80.00	\$ 80.00 <i>x</i>

150

TOTAL \$ 1,020.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,400.00	<i>1000</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	<i>700</i>
3	WIRNING, BULB CHECKING	\$ 180.00	<i>30</i>
4	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>x</i>
5	REAR CHASSIS ALIGHMENT	\$ 250.00	<i>x</i>
6	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX FUEL TANK TO FACILIATE FENDER REPLACEMENT	\$ 80.00	<i>x</i>
8	REMOVE AND REFIX REAR SIDE PANEL GLASS	\$ 100.00	<i>50</i>
9	REMOVE AND REFIX <i>Undercarriage</i>	\$ 400	<i>250</i>

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBF7005K**
MODEL : **NISSAN NV200**
DATE OF ACCIDENT : 03.11.2022
TIME OF ACCIDENT : 17:10 HRS

10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL \$ 5,570.00

2080

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,302.84
TOTAL LABOUR COST : \$ 5,570.00
TOTAL REPAIR COST : \$ 17,872.84

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G

2/s 08/11/22

08 Days,

total: 8913.76

4/s: 7.1K