

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011178/APA3Q2**Date:** 20/04/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SPCM1000000944
Claimant Vehicle No :	YM9310G	Insured Vehicle No :	XB9376L
Date of Loss:	28/10/2022	Nature of Claim:	TP
		Claim No:	202222007794

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YM9310G	Engine No:	6M60130795
Make & Model:	MITSUBISHI FM65FM1RDEA, 7.5 D (M)	Chassis No:	FM65FMB00092
Reg. Date:	16/10/2008 (Man. Year: 2008)	Odometer:	646769 km
Colour:	White		
Engine Capacity:	7545 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,541.49	13,552.00	15,989.49	54.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	1,620.00	1,990.00	55.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,151.49	15,172.00	17,979.49	54.23
Approved Total (Overridden) (S\$)		9,250.00		
Nett Amount (S\$)	33,151.49	9,250.00	23,901.49	72.10
+ Loss of Use (11.0 x S\$120.00/day) (S\$)		1,320.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		10,608.45		
Global Sum Settlement (S\$)		10,600.00		

INSPECTION

Date of Assignment:	07/11/2022	
Date Inspected:	07/11/2022	Inspected At: 2 buroh crescent
Estimated Period of Repair:	9.0 days	Repairer: HD Perfect Autowork Pte Ltd (HQ)

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Apr 2023)	
Parts:	N/A	MITSUBISHI FM65FM1RDEA 7.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YM9310G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE HOLDER	Dented	856.00 FL	*856.00 FL
2	2		*TAIL LAMP	Not Necessary	490.60 FL	*- FL
3	2		*TAIL LAMP SUPPORT BRACKET	Not Necessary	372.80 FL	*- FL
4	1		*REAR NUMBER PLATE	Dented	50.00 FS	*50.00 FS
5	2		*REAR BOX OPEN DOOR (SPECIAL TYPE) (COMPLETE SET)	Deformed	11,600.00 FS	*6,000.00 FS
6	2		*REAR BOX OPEN DOOR LOCK CATCH (SPECIAL TYPE)	Bent	300.00 FS	*250.00 FS
7	2		*REAR BOX OPEN DOOR LOCK	Bent	1,700.00 FS	*900.00 FS
8	1		*REAR BOX OPEN DOOR 60KM/H	Necessary	30.00 FS	*10.00 FS
9	1		*REAR BOX OPEN DOOR FRAME (STANDARD STEEL) (SPECIAL TYPE)	Dented	6,800.00 FS	*1,800.00 FS
10	1		*SET REAR OPEN DOOR STICKER	Necessary	4,800.00 FS	*2,500.00 FS
11	1		*REAR BOX LOVER BEAM	Dented	2,800.00 FS	*1,400.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)						29,799.40 13,766.00
- List Item Discount on L Items 15.00/25.00% (\$\$)						257.91 214.00
Total Parts (\$\$)						29,541.49 13,552.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD,CUT ,ADJUST ,KNOCK	New	1,400.00	900.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,400.00	400.00
3	TRANSFER REAR DOOR MECHANISM	New	380.00	200.00
4	REAR CHASSIS ALIGHMENT	New	250.00	120.00
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			3,610.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >